



MISSISSIPPI-KASKASKIA-ST. LOUIS BASIN

AD A 105285

GOOSE CREEK LAKE DAM ST. FRANCOIS COUNTY, MISSOURI MO 30297

PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY INSPECTION



United States Army Corps of Engineers

..Serving the Army ..Serving the Nation

St. Louis District



D

PREPARED BY: U.S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

Original contains color plates: All DTIC reproductions will be in black and white

JUNE 1981

DISTRIBUTION STATEMENT A

Approved for public releases

Distribution Unlimited

81 10 7 091

IN PILE COPY



SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)	READ INSTRUCTIONS
REPORT DOCUMENTATION PAGE	BEFORE COMPLETING FORM
I. REPORT ROMDER	3. RECIPIENT'S CATALOG NUMBER
AD-AZO	3 83
A. TITLE (and Subtitle)	S. TYPE OF REPORT & PERIOD COVERED
A. TITLE (and Substite) Phase I Dam Inspection Report	· · · · · · · · · · · · · · · · · · ·
National Dam Safety Program	Final Repart,
Goose Creek Lake Dam (MO 30297)	6. PERFORMING ORG. PEPORT NUMBER
St. Francois County, Missouri	8. CONTRACT OR GRANT NUMBER(4)
7. Author(s)	a. CONTRACT ON SHAWY WELLS
Woodward-Clyde Consultants	1/2
	DACW43-81-C-0039 Pill
9. PERFORMING ORGANIZATION NAME AND ADDRESS	10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
U.S. Army Engineer District, St. Louis	AREA & WORK UNIT NUMBERS
Dam Inventory and Inspection Section, LMSED-PD	}
210 Tucker Blvd., North, St. Louis, Mo. 63101	
11 CONTROLLING OFFICE NAME AND ADDRESS	12. REPORT DATE
U.S. Army Engineer District, St. Louis	June 1981/
Dam Inventory and Inspection Section, LMSED-PD	13. NUMBER OF PAGES
210 Tucker Blvd., North, St. Louis, Mo. 63101	Approximately 70 15. SECURITY CLASS. (of this report)
14. MONITORING AGENCY NAME & ADDRESS(II different from Controlling Office)	15. SECURITY CEASS. (or una report)
(/2 Mal	UNCLASSIFIED
	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
A second	SCHEDULE
Approved for release; distribution unlimited.	- r 12 Gillion 10 1
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different in	rom Report)
	and the second of the second o
National Dam Safet Creek Lake Dam (MC Mississippi - Kask Mississippi - Kask	-1-fo St. Louis
postn St. Francos	re domine);
Phase I Inspection	a keport.
19. KEY WORDS (Continue on reverse side if necessary and identify by block number	or)
Dam Safety, Lake, Dam Inspection, Private Dams	
This report was prepared under the National Programment Non-Federal Dams. This report assesses the general respect to safety, based on available data and on determine if the dam poses hazards to human life	am of inspection of all condition of the dam with visual inspection, to

DD 1 JAN 73 1473 EDITION OF 1 NOV 65 IS OBSOLETE

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Date Entered)

 ICATION OF THIS PAGE(When Data Entered)	
•	
$ au = \mathbf{r}$	

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CL FICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

- General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.
 - Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.
 - Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.
- Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.
- Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E,"AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.
- Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.
- Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.
- Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.
- Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.
- Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of t. performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.
- Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634. "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.
- Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")
 - Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.
 - Block 13. Number of Pages. Enter the total number of pages.
- Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.
- Blocks 15 & 15s. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.
- Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."
- Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."
- Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .
- Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.
- Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified should consist of publicly- releasable information. If the report contains a significant bibliography or literature survey, mention it. ... For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.



DEPARTMENT OF THE ARMY

ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 TUCKER BOULEVARD, NORTH
ST. LOUIS, MISSOURI 62101

MEPLY TO ATTENTION O

SUBJECT: Goose Creek Lake Dam Phase I Inspection Report


This report presents the results of field inspection and evaluation of the Goose Creek Lake Dam (MO 30297).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- a. Spillway will not pass 50 percent of the Probable Maximum Flood without overtopping the dam.
 - b. Overtopping of the dam could result in failure of the dam.
- c. Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY:	SIGNED	17 JUL 1981
	Chief, Engineering Division	Date
APPROVED BY:	SIGNED	17 JUL 1981
• •	Colonel, CE, Commanding	Date



myster of a constant and a constant



GOOSE CREEK LAKE DAM

St Francois County, Missouri Missouri Inventory No. 30297

Phase I Inspection Report National Dam Safety Program

Prepared by

Woodward-Clyde ConsultantsChicago, Illinois

Under Direction of St Louis District, Corps of Engineers

for Governor of Missouri June 1981

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams for Phase I Investigations. Copies of these guidelines may be obtained from the Office of the Chief of Engineers, Washington, D. C., 20314. The purpose of a Phase I investigation is not to provide a complete evaluation of the safety of the structure nor to provide a guarantee on its future integrity. Rather the purpose of the program is to identify potentially hazardous conditions to the extent they can be identified by a visual examination. The assessment of the general condition of the dam is based upon available data (if any) and visual inspections. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify the need for more detailed studies. In view of the limited nature of the Phase I studies no assurance can be given that all deficiencies have been identified.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with any data which may be available to the inspection team. In cases where the reservoir was lowered or drained prior to inspection, such action removes the normal load on the structure, as well as the reservoir head along with seepage pressures, and may obscure certain conditions which might otherwise be detectable if inspected under the normal operating environment of the structure.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected, so that corrective action can be taken. Likewise continued care and maintenance are necessary to minimize the possibility of development of unsafe conditions.

PHASE I REPORT NATIONAL DAM SAFETY PROGRAM

Name of Dam State Located County Located Stream Date of Inspection Goose Creek Lake Dam Missouri St Francois Goose Creek 27 April 1981

Goose Creek Lake Dam, Missouri Inventory Number 30297, was inspected by Richard Berggreen (engineering geologist), Craig Fulthorpe (geotechnical engineer), Jean-Yves Perez (geotechnical engineer), and Maryann Rivera (hydrologist). The dam is an earth embankment constructed to impound a reservoir for recreational purposes.

The dam inspection was made following the guidelines presented in the "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed by the Chief of Engineers, US Army, Washington, DC, with the help of federal and state agencies, professional engineering organizations, and private engineers. The resulting guidelines represent a concensus of the engineering profession. These guidelines are intended to provide for an expeditious identification of those dams which may pose hazards to human life or property, based on available data and a visual inspection. In view of the limited scope of the study, no assurance can be given that all deficiencies have been identified.

The St Louis District (SLD), Corps of Engineers, has classified this dam as having a high hazard potential. The potential damage zone length estimated by the SLD extends approximately nine miles downstream. Located within this estimated damage zone are a dam under construction (MO 31078) approximately one mile downstream, at least ten dwellings and numerous out-buildings. The contents of a portion of the damage zone were verified by aerial reconnaissance. The potential for loss of life and property is high in the event of dam failure.

Goose Creek Lake Dam is in the intermediate size classification based on its height of approximately 52 ft and storage capacity of 1900 ac-ft. The intermediate size classification criteria are: height between 40 and 100 ft, or storage capacity between 1000 and 50,000 ac-ft.

The results of the visual inspection indicate the embankment is in fair to good condition. No evidence of cracking of the embankment was noted, although two areas which might be old slumps were identified on the downstream slope. No animal burrows or sinkholes were found. Motorcycle traffic has worn a path on the downstream slope and may contribute to accelerated erosion in this area. The horizontal alignment of the crest appears undeformed; settlement appears to have lowered the center of the dam crest 18 to 24 in. below the ends of the dam. Drainage from the right abutment flows in a channel along the junction of the embankment and right abutment. Erosion in this channel has steepened the toe of the slope and may have contributed to shallow slumping in this area. No erosion protection has been installed on the upstream slope, but as of the visual inspection, wave erosion was relatively minor.

Hydraulic/hydrologic analyses indicate the dam will be overtopped by a flood which produces greater than 16 percent of the Probable Maximum Flood (PMF). The guidelines require intermediate size dams to store and pass 100 percent of the PMF without overtopping the embankment. The PMF is defined as the flood event that may be expected to occur from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The analyses also indicate the dam will not be overtopped by the 1 percent probability-of-occurrence flood (100 year flood). On the basis of this overtopping analysis the dam is considered to be in only fair condition. Overtopping of the depth and duration calculated for 100 percent of the PMF is considered likely to result in sufficient erosion to cause failure of this dam.

Based on our evaluation of the information obtained from the visual inspection and other available information, the following specific recommendations are made for Goose Creek Lake Dam. The recommendation regarding the spillway capacity should be implemented immediately. The other recommendations should be addressed without undue delay.

1. Prepare a detailed hydraulic/hydrologic analysis and design a spillway and discharge channel system capable of passing 100 percent of the PMF without overtopping the dam. The spillway should be protected from erosion and/or obstruction.

- 2. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" should be performed and made a matter of record. Such analyses should consider all appropriate loading conditions, including seismic loads, and should be made by an engineer experienced in the design and construction of earth dams.
- 3. Erosion control measures should be designed and implemented in the area at the junction of the embankment and right abutment.
- 4. Repair the path worn on the downstream slope and control vehicle traffic on the embankment.

It is also recommended that a formal program of periodic inspections and maintenance be developed and initiated at this facility. This program should be prepared by and performed under the guidance of an engineer experienced in the design, construction, and maintenance of earth dams. It should include but not be limited to the following items.

- 1. Inspect the embankment for evidence of cracking or slumping, settlement of the dam crest, or other evidence of slope instability. These inspections should specifically include the areas of shallow slumping noted in this Phase I inspection report (Fig. A-1).
- 2. Monitor the area of seepage near the toe of the dam to identify any changes in the amount of seepage or turbidity (soil) in the seepage water.
- 3. Remove the small trees growing on the downstream slope of the dam before they become large enough to pose a hazard to the stability of the dam. Vegetation on the dam should be maintained to the extent that it does not interfere with the recommended inspection program.
- 4. Maintain the spillway and discharge channel free of obstructions to flood flows.

5. Monitor wave erosion on the upstream slope and provide erosion control measures in the event erosion becomes significant or poses a hazard to the stability of the dam.


WOODWARD-CLYDE CONSULTANTS

Rechard of Buggree

Richard G. Berggreen Registered Geologist, No 3572, CA

Jean-Yves Perez, PE No. 62-34675, IL

Vice President



OVERVIEW GOOSE CREEK LAKE DAM

MISSOURI INVENTORY NUMBER 30297

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM GOOSE CREEK LAKE DAM - MISSOURI INVENTORY NO. 30297 TABLE OF CONTENTS

Paragraph No.	<u>Title</u>	Page No.
	SECTION 1 - PROJECT INFORMATION	
1.1 1.2 1.3	General Description of Project Pertinent Data	1 2 4
	SECTION 2 - ENGINEERING DATA	
2.1 2.2 2.3 2.4 2.5	Design Construction Operation Evaluation Project Geology	7 7 7 8 8
	SECTION 3 - VISUAL INSPECTION	
3.1 3.2	Findings Evaluation	10 13
	SECTION 4 - OPERATIONAL PROCEDURES	
4.1 4.2 4.3 4.4 4.5	Procedures Maintenance of Dam Maintenance of Operating Facilities Description of Any Warning System in Effect Evaluation	14 14 14 14 15
	SECTION 5 - HYDRAULIC/HYDROLOGIC	
5.1	Evaluation of Features	16
	SECTION 6 - STRUCTURAL STABILITY	
6.1	Evaluation of Structural Stability	19

Paragraph No.	<u>Title</u>	Page No.
	SECTION 7 - ASSESSMENT/REMEDIAL MEASURES	
	n Assessment nedial Measures	21 22
REFERENCES		25
FIGURES		
2. Drai 3-A. Plan 3-B. Sect	Location Map inage Basin and Site Topography n and Profile of Dam tions of Dam, Spillway and Discharge Channel ional Geologic Map	
APPENDICES		
A Figu	re A-1: Photo Location Sketch	
Pho	tographs	
1. 2.	Clay and silt soil with gravel to cobble and boulder-size rocused in the embankment construction. Fault exposed in spillway cut. Fault dips vertically, strikes separates white quartzite with thin soil cover on the right fi	N55 ⁰ W,
3.	with thick red-brown soil cover on the left. Downstream slope of dam showing grass, weed and small tre Note scattered boulders in embankment fill and downhill inc	
4.	of some trees. Looking south from left abutment. Downstream slope and toe of dam showing cattail vegetation lush green vegetation on toe of dam, and boulders in embandary.	
5 .	Looking west, upstream. View of upstream slope of dam. Note slight dip in dam cress Note also rocky fill on near half of dam, apparently added to crest. High water line, far side of dam, has not become well	o raise dam
6.	on new material. Looking south-southeast from entrance of Spillway excavated at left (north) end of dam. Note remnan spillway weir in front of observer. Looking southwest from	spillway.
7.	of discharge channel. Remnants of concrete spillway weir shown in Photo 6. Rese	
8.	out of picture to the right. Downstream channel flows to the Steep rocky slopes which surround portions of the reservoir. northwest from the entrance of the spillway.	
9.	Downstream discharge channel. Note small soil slumps along of the banks of the channel. Looking east, downstream.	g portions
10.	Dam (MO 31078) under construction downstream from Goose Dam. Looking west.	e Creek
11.	Typical contents of downstream damage zone.	

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM GOOSE CREEK LAKE DAM, MISSOURI INVENTORY NO. 30297

SECTION 1 PROJECT INFORMATION

1.1 General

- a. <u>Authority.</u> The National Dam Inspection Act, Public Law 92-367, provides for a national inventory and inspection of dams throughout the United States. Pursuant to the above, an inspection was conducted of Goose Creek Lake Dam, Missouri Inventory Number 30297.
- b. Purpose of Inspection. "The primary purpose of the Phase I investigation program is to identify expeditiously those dams which may pose hazards to human life or property... The Phase I investigation will develop an assessment of the general condition with respect to safety of the project based upon available data and a visual inspection, determine any need for emergency measures, and conclude if additional studies, investigations and analyses are necessary and warranted" (Chapter 3, "Recommended Guidelines for Safety Inspection of Dams").
- Evaluation criteria. The criteria used to evaluate the dam were established in the "Recommended Guidelines for Safety Inspection of Dams," and Engineering Regulation No. 1110-2-106 and Engineering Circular No. 1110-2-188, "Engineering and Design National Program for Inspection of Non-Federal Dams," developed by the Office of Chief of Engineers, Department of the Army; and "Hydrologic/Hydraulic Standards Phase I Safety Inspection of Non-Federal Dams," prepared by the St Louis District (SLD), Corps of Engineers. These guidelines were developed with the help of several federal agencies and many state agencies, professional engineering organizations, and private engineers.

1.2 Description of Project

a. Description of dam and appurtenances. Goose Creek Lake Dam is an earth embankment impounding a lake for recreational purposes. The area surrounding the lake is being developed for permanent and vacation residences. The dam crest varies from elevation 756.8 ft to 752.3 ft, being lower near the center of the dam. The height of the dam at the maximum section is approximately 52 ft. The crest of the dam varies from 10 to 20 ft in width. The downstream slope of the dam at the maximum section is approximately 3(H) to 1(V). The upstream slope from the crest to the waterline is approximately 4(H) to 1(V). The embankment was constructed of gravelly to bouldery silt and clay residual soil and is covered for the most part with grass and weed vegetation. A number of small trees are also growing on the downstream slope. There is no riprap or other erosion control measure on the upstream slope.

The spillway is an uncontrolled broad trapezoidal cut in weathered bedrock in the left abutment (as the observer faces downstream). A vertical dipping fault is exposed in the spillway cut but does not appear to trend under the dam. The downstream discharge channel is in weathered rock and residual soil and the banks of the channel may be subject to small slumps during heavy flows through the channel.

No other appurtenant structures were identified at this dam.

- b. Location. The dam is located on Goose Creek, in Section 26, T38N, R6E, on the USGS Lawrenceton, Missouri 7.5-minute quadrangle map (1964). The dam and reservoir are in the Goose Creek development north of Missouri State Highway Y, about 2.5 miles east of the town of French Village in St Francois County, Missouri (Fig. 1).
- c. <u>Size classification</u>. The dam is classified intermediate size based on its height of approximately 52 ft and storage capacity of 1900 ac-ft. The intermediate size classification includes dams between 40 and 100 ft in height, or having storage capacities between 1000 and 50,000 ac-ft.

- d. Hazard classification. The St Louis District (SLD), Corps of Engineers, has classified this dam as having a high hazard potential; we concur with this classification. The damage zone length, as determined by the SLD, extends approximately nine miles downstream. Located within this estimated damage zone are a dam (MO 31078), and at least ten dwellings and numerous out-buildings. The contents of a portion of the downstream damage zone were verified by aerial reconnaissance. The potential for loss of life and property damage is high in the event of sudden failure of this dam.
- e. Ownership. The dam is reportedly owned by the Goose Creek Land Company, 210 A Main Street, Festus, Missouri 63028. Correspondence should be to the attention of Mr Stu McCaleb.
- f. Purpose of dam. The lake impounded by the dam is used for recreational purposes by the surrounding residential community.
- g. Design and construction history. No design drawings or plans or construction reports were available for this dam. All information on the design and construction was obtained from Mr Stu McCaleb of the Goose Creek Land Company.

The dam was reported to have been designed by Mr Dewey Craig, resident surveyor for the Goose Creek development. Mr Craig died two to three years ago. No plans were found for Mr Craig's design. He reportedly surveyed-in and staked the limits of the embankment fill, and turned construction of the dam over to Black Construction Company of Bismark, Missouri. Black Construction Co was reported to no longer be active.

According to Mr McCaleb, the dam was constructed in 1970 and he was present for most of the construction. The dam was constructed as a homogeneous impermeable embankment of locally obtained gravelly to bouldery silt and clay residual soil. A cut-off trench was excavated through the foundation soils to bedrock, approximately one scraper blade wide (estimated at 10 ft wide). Mr McCaleb did not recall any drains or low level outlets at the dam.

The spillway was excavated by blasting in the left abutment. The spillway was deepened approximately 2 ft in 1975 also by blasting to lower the lake level. No significant siltation was noted at the upstream end of the reservoir following the lowering of the lake.

Some settlement of the embankment has occurred. Remedial measures included raising the dam crest approximately 18 to 24 in. about 2 years ago.

No other records or evidence of construction or modifications were found during the visual inspection.

h. Normal operating procedures. No facilities requiring operation were identified at this dam. Normal procedure is to pass flood flows through the ungated spill way at the left abutment.

1.3 Pertinent Data

a. Drainage area. 4.8 mi²

b. Discharge at damsite.

Maximum known flood at damsite	Unknown
Warm water outlet at pool elevation	N/A (Not applicable)
Diversion tunnel low pool outlet at pool elevation	N/A
Diversion tunnel outlet at pool elevation	N/A
Gated spillway capacity at pool elevation	N/A
Gated spillway capacity at maximum pool elevation	N/A
Ungated spillway capacity at maximum pool elevation	1880 ft ³ /sec
Total spillway capacity at maximum pool elevation	1880 ft ³ /sec

c. Elevation (ft above MSL).

Top of dam	752.3 to 756.8
Maximum pool-design surcharge	N/A
Full flood control pool	N/A
Recreation pool (spillway crest)	744.7

Spillway crest (gated)	N/A
Upstream portal invert diversion tunnel	N/A
Downstream portal invert diversion tunnel	N/A
Streambed at centerline of dam	Unknown
Maximum tailwater	Unknown
Toe of dam at maximum section	700.5

d. Reservoir.

Length of maximum pool	6800 ft
Length of recreation pool	5500 ft
Length of flood control pool	N/A

e. Storage (acre-feet).

Recreation pool (spillway crest)	1200
Flood control pool	N/A
Design surcharge	N/A
Top of dam	1900

f. Reservoir Surface (acres).

Top of dam	108
Maximum pool	108
Flood control pool	N/A
Recreation pool	68
Spillway crest	68

g. Dam.

Туре	Homogeneous earth embankment
Length	583 ft
Height	51.8 ft
Top width	Varies from 10 ft (near spillway) to 20 ft (near right abutment)
Side slopes	Downstream 2.5 - 3.5(H) to 1(V)

Upstream 3 - 5(H) to 1(V) from crest to

water level

Zoning

None, homogeneous embankment

Impervious core

Homogeneous impervious section

Cutoff

Trench to bedrock, approximately 10 ft

wide

Grout curtain

None

h. <u>Diversion and regulating tunnel</u>.

Type None
Length N/A
Closure N/A
Access N/A

Regulating Facilities

i. Spillway.

Type

Uncontrolled trapezoidal cut in left

abutment

N/A

Length of weir

35 ft at base, 55 ft at elevation of

minimum top of dam

Crest elevation

744.7 ft

Gates

and the state of the control of the control of the control of the state of the stat

None

Downstream channel

Unlined channel in weathered bedrock

and residual soil

j. Regulating outlets.

None.

SECTION 2 ENGINEERING DATA

2.1 Design

The dam was reportedly designed by Mr Dewey Craig, resident surveyor for the Goose Creek development. Mr Craig died 2 to 3 years ago. No records or design plans were available for review. Mr Craig reportedly staked the limits of the embankment fill prior to beginning of construction.

2.2 Construction

The dam was constructed by Black Construction Company, Bismark, Missouri, in 1970. Black Construction Co was described by Mr McCaleb as no longer active.

Mr McCaleb was present for most of the construction and provided the following information. The dam consists of a homogeneous embankment constructed of locally obtained gravelly to bouldery silt and clay residual soil. A keyway was excavated to bedrock and was about one pull-scraper wide, (± 10 ft). Mr McCaleb has no recollection of any drains or low-level outlets at this facility.

The spillway was excavated into the left abutment by blasting. The spillway was lowered an additional 2 ft in 1975, also by blasting.

2.3 Operation

There are no records of flow history through the spillway. Flood flows are passed through the ungated spillway. No facilities requiring operation were identified at this dam.

2.4 Evaluation

- a. Availability. Design and construction data on Goose Creek Lake Dam were limited to interviews with Mr Stu McCaleb of the Goose Creek Land Company. No design plans or drawings or construction reports were available for review.
- b. Adequacy. The available data are insufficient to evaluate the adequacy of design of Goose Creek Lake Dam. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not on record, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions, including seismic loads, and made a matter of record. The analyses should be performed by an engineer experienced in the design and construction of earth dams.
- c. <u>Validity.</u> There was no reason to question the validity of the information obtained from Mr McCaleb. However, the information was incomplete.

2.5 Project Geology

The dam site is located on the northern flank of the Ozark structural dome. According to the Geologic Map of Missouri (1979), the area of the dam site lies in close proximity to the contact between the Cambrain age Potosi and Eminence Dolomite formations and the Ordovician age Gasconade Dolomite formation.

The Potosi Dolomite, a light gray, medium- to fine-grained dolomite, typically contains an abundance of quartz druse associated with chert deposits within the formation. The Eminence Dolomite conformably overlies the Potosi Dolomite and is similar in appearance but contains less chert and quartz. The Gasconade Dolomite is a light brownish gray, cherty dolomite and can be divided into a lower coarsely crystalline portion which is extremely cherty, and an upper finely crystalline portion which is relatively less cherty. A sandstone unit (the Gunter member) forms the lowermost part of the formation.

The soil exposed at the dam site is a gravelly to bouldery silt and clay residual soil (CL). The soil was sampled and classified in the field. It is mapped and described in the Missouri General Soil Map and Soil Association Descriptions (1979) as the Union-Goss-Gasconade-Peridge Soil Association. A short distance west of the dam site the Peridge-Cantwell-Gasconade Soil Association becomes predominant.

There are a number of faults and folds mapped in the area of the dam site. The St. Genevieve Fault System, a complex network of generally NW-SE trending faults, is mapped less than 1 mile east of the dam site. A fault was observed at the spillway of the dam during the field investigation, and may be a branch of the St. Genevieve system.

A NW-SE trending structure called the Rugley School Fault Block or Fault is mapped on the Structural Features Map of Missouri (1971) about 2 miles northwest of the dam site. A number of faults associated with the NW-SE trending Ditch Creek Fault System are mapped within 4-6 miles west and northwest of the dam site. These faults, like most others in the Ozark region, are within Precambrian and Paleozoic formations, and are likely Paleozoic in age. They are not considered seismically active.

There are two anticlines mapped in the vicinity of the dam site on the Structural Features Map of Missouri. The northern portion of the NW-SE trending Farmington Anticline is located approximately 3.5 miles southwest of the dam site, and the southernmost extension of the NE-SW trending Plattin Creek Anticline is located about 6 miles northwest of the dam site.

The dam is located approximately 85 miles north of the line of epicenters for the very large New Madrid earthquakes of 1811 and 1812. A recurrence of an earthquake of the magnitude of the New Madrid events could cause damage to this dam, but an assessment of this risk is beyond the scope of this Phase I investigation.

SECTION 3 VISUAL INSPECTION

3.1 Findings

- a. General. A visual inspection was made of Goose Creek Dam on 27 April 1981.

 No representative of the owner of the dam was present during the inspection.

 The inspection indicates the dam is in generally fair to good condition.
- b. <u>Dam.</u> The dam is an earth embankment approximately 52 ft in height. It was constructed of locally obtained silt and clay (CL) residual soil containing numerous gravel- to boulder-size rock fragments (Photo 1). Boulders to several feet in diameter were noted in portions of the embankment fill. The fine fraction of the fill is residual clay and silt, red-brown to tan, slightly plastic to non-plastic, developed by weathering of the carbonate and sandstone bedrock in the area.

Bedrock exposed in the spillway cut indicates two rock types are present in the area. The two rock types are separated by a vertical-dipping fault striking N55° W (Photo 2). Upstream or west of the fault and underlying the dam, the bedrock consists of hard white quartzite, perhaps the Gunter member of the Gasconade Formation. The soil developed on the quartzite is relatively thin, sandy, and light gray to tan in color. Downstream or east of the fault, the bedrock consists of deeply weathered dolomite, either the Gasconade or Eminence Dolomite. Relative movement on the fault could not be determined from the limited exposures in the spillway.

The upstream and downstream slopes of the embankment are covered by grass and weed vegetation with scattered bare spots (Photo 3). Small trees are also scattered across the downstream slope. These trees should be removed before they become large enough to pose a hazard to the dam.

A motorcycle or off-road vehicle path was noted on downstream slope of the dam. This traffic should be kept off the dam as erosion will concentrate in the vehicle tracks.

The embankment materials and vegetative cover indicate the dam is moderately resistant to erosion by running water. Only minor rilling erosion was noted on the downstream slope of the dam. Runoff from the right abutment (as the observer faces downstream) flows into a channel at the junction of the downstream slope of the embankment and right abutment. This channel has eroded the embankment and locally oversteepened the toe of the slope (see Fig. A-1).

No cracking was identified on the dam. However, two areas of indistinct scarp-like features were noted (see Fig. A-1). One area approximately 50 ft wide and extending about half up the slope of the dam appears to be a shallow slump associated with the oversteepening at the toe of the right side of the dam. A second area approximately 100 ft wide and extending about two-thirds up the slope near the left end of the dam also appeared to be a shallow slump. Some of the small trees in the body of this slump were inclined down slope. The lack of distinct scarps or other slump features indicates these are likely older slumps that have not moved recently. However, the areas should be periodically inspected to identify any renewed movement.

Evidence of seepage was limited to an area of cattail vegetation at the toe of the dam (Photo 4). Although no flow was noted during the inspection, lush green vegetation at the toe of the dam suggests a slow rate of seepage may be present. The cattail vegetation could also be the result of ponding of abutment and slope drainage in a low at the toe of the dam. In either case, the seepage did not appear sufficient to pose a hazard to the stability of the dam.

No disruption was noted in the horizontal alignment of the dam crest. However, some settlement was reported by the dam owner's representative, Mr Stu McCaleb, and the crest of the dam appears lowest near the maximum section. Mr McCaleb reported 18 to 24 in. of fill was added to the dam crest approximately 2 years ago, but the field survey conducted for this report indicated the center of the dam is still approximately 18 to 24 in. lower than the ends of the dam (Fig. 3A). During the visual inspection an area of rocky fill was noted from about the middle of the dam crest to the left (spillway) end of the dam, specifically on the upstream slope (Photo 5). This appears to be the area where new fill has been added to the crest of the dam.

No evidence of animal burrows or sinkhole development was noted on the embankment during the visual inspection.

No riprap or other erosion control measures have been installed along the upstream slope. Some wave erosion has occurred about 2 ft above the current lake level. This may have occurred when the lake level was approximately 2 ft higher. It was reported by Mr McCaleb that the spillway sill was lowered about 2 ft several years ago to remove weeds at the upstream end of the reservoir. Wave erosion will likely continue to occur, but at present does not appear to pose a significant hazard to the dam.

c. Appurtenant structures. The spillway for this dam is a trapezoidal cut in weathered bedrock at the left or north end of the dam (Photo 6). The spillway is about 35 ft wide at the base and 55 ft wide at the elevation of the minimum top of dam. There are no gates or other control structures at the spillway. The remnants of an old concrete weir can be seen in the spillway (Photo 7), but it was either removed by man or destroyed by erosion. It was reported by Mr McCaleb that the spillway crest was lowered several years ago to allow clearing of weeds in the upstream ends of the reservoir. This lowering may have been accomplished by removal of the concrete weir.

No other appurtenant structures were identified at this dam.

d. Reservoir area. The area surrounding the reservoir is being developed as a residential/vacation home community. Scattered development of lots and road building will likely continue to supply limited sediment to the lake. The lowering of the lake several years ago showed no evidence of siltation of the upstream end of the reservoir.

The slopes surrounding the reservoir vary from quite steep, 1(H) to 1(V), (Photo 8), to fairly gentle, flatter than 5 (H) to 1 (V). No evidence of unstable slopes adjacent to the reservoir was noted.

e. <u>Downstream channel</u>. The channel downstream of the spillway is a deeply eroded trapezoidal channel along the left side of the valley (Photo 9). Erosion

appears to be continuing in the channel and small slumps were noted along portions of the channel walls. However, none of these slumps appears large enough to pose a significant obstruction to flow in the channel.

3.2 Evaluation

The visual inspection indicates the dam and appurtenant structures are in fair to good condition. No evidence was noted of animal burrows, sinkhole development, significant erosion or seepage. Some erosion at the junction with the right abutment has caused local oversteepening of the toe of the downstream slope. The embankment appears to have experienced some settlement, with the dam crest near the maximum section being approximately 18 to 24 in. lower than the ends of the dam.

Two indistinct slumps were noted on the downstream slope. These slumps lack well defined scarps or other distinct slump features, suggesting they are old shallow slumps. Although these slumps do not appear presently active, periodic inspection is recommended to detect renewed movement, if any. The spillway was excavated in weathered bedrock at the left abutment and does not appear subject to significant erosion during flood flows. The downstream channel below the spillway was excavated in weathered bedrock and residual soil. Erosion and slumping of the banks of this channel were noted during the visual inspection. However, the slumps appear to be small and are not considered sufficient to be a significant obstruction to flow.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Procedures

No records are available of operating procedures at this facility. Water level in the reservoir is controlled by flow through the ungated spillway. Normal operating procedure is to allow natural drainage through the spillway.

4.2 Maintenance of Dam

There is no formal plan for inspection and maintenance of the dam. Mr McCaleb reported that necessary maintenance is performed by the construction crew or foreman working for the Goose Creek development. Recent maintenance included the addition of 18 to 24 in. of fill to the dam crest to raise the dam following gradual settlement.

No riprap or other erosion control measure has been installed on the upstream slope. Wave erosion to date has not been significant and the area does not pose a hazard to the safety of the dam at present. However, some maintenance may be required as erosion progresses.

4.3 Maintenance of Operating Facilities

No facilities requiring operation were identified at this dam.

4.4 Description of Any Warning System in Effect

The visual inspection did not identify any warning system in effect at this dam.

4.5 Evaluation

There is no formal maintenance or inspection program in effect at this facility. At present informal inspection and maintenance needs are performed by construction crews and foreman for the development company. However, as the development nears completion and these personnel are no longer available, the implementation of a formal inspection and maintenance program will be necessary to assure the continued monitoring of the facility. It is recommended such a program be developed and implemented under the guidance of an engineer experienced in the construction and maintenance of earth dams.

The feasibility of a practical and effective warning system should also be evaluated, to alert downstream residents in the event unsafe conditions develop at this dam.

SECTION 5 HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

- a. Design data. No hydrologic or hydraulic design data were available for evaluation of this dam or reservoir; however, dimensions of the dam were surveyed. The survey data were supplied by James F. McCaul III and Associates, Potosi, Missouri. Other relevant data were measured during the visual inspection or estimated from topographic mapping. The maps used in the analyses were the USGS Lawrenceton and French Village, Missouri 7.5-minute quadrangle maps.
- b. Experience data. No recorded rainfall, runoff, discharge, or pool stage historical data were found for this reservoir. There was no evidence or record of past overtopping of the embankment.

c. Visual observations.

- 1. <u>Watershed</u>. The watershed consists of scattered residential and vacation homes, pasture and dense natural woodlands. The area of the reservoir is about 3 percent of the total drainage area of 4.8 mi². For the purposes of the overtopping analysis, the watershed was divided into two sub-basins, the main Goose Creek basin, and a small tributary basin to the north (see Fig. 2).
- 2. Reservoir. The reservoir, dam and spillway are best described by the maps and photographs enclosed herewith. The reservoir is used for recreational purposes.
- 3. Spillway. An open channel spillway is located at the left (north) end of the dam. The spillway discharge channel drops steeply within a short distance. The controlling section for discharge is slightly downstream of the entrance of the spillway, at the steep drop in gradient of the channel, Section EE of Fig. 3-B.

d. Overtopping potential. One of the primary considerations in the evaluation of this dam is the assessment of the potential for overtopping and possible consequent failure by erosion of the embankment. The lowest portion of the dam is near the middle of the dam and was considered to be the top of the dam for the purpose of determining overtopping potential. Since the spillway of this dam was blasted into bedrock, erosion of the spillway due to high velocity discharge is not expected to be a major consideration.

Hydraulic analyses of this dam for the 1 and 10 percent probability-ofoccurrence and Probable Maximum Floods (PMF) were all based on initial water surface elevations equal to the minimum elevation of the spillway section. The result of the analysis indicates that a flood of greater than 16 percent of the PMF will overtop the dam. The PMF is defined as the flood event that may be expected to occur from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region. The "Recommended Guidelines for Safety Inspection of Dams" require high hazard potential, intermediate size dams to pass a spillway design flood of 100 percent of the PMF. The analyses also indicate that the spillway will pass the 1 percent probability-of- occurrence (100 year recurrence interval) flood event without overtopping the dam. The 1 percent probabilityof-occurrence flood event is the flood event that has I percent chance of occurring in any year, or occurs on the average once every 100 years. The total spillway capacity at maximum pool elevation is approximately 1900 ft³/sec.

The following overtopping data for various flood events were computed for the dam assuming no erosion of the dam or spillway.

Precipitation Event	Maximum Reservoir Elevation, ft, (MSL)	Maximum Depth Over Dam, ft	Maximum Outflow, ft ³ /sec	Duration of Overtopping, hrs
1% Prob	752.0	0	1,715	0
16% PMF	752.1	0	1,804	0
50% PMF	755.6	3.3	9,200	7.0
100% PMF	757.4	5.1	18,600	10.3

It should be noted that at 100 percent of the PMF the depth of flow during overtopping may reach 5.1 ft and the dam may be overtopped for 10.3 hours. Overtopping flows of this depth and duration is considered likely to result in sufficient erosion to cause failure of the dam.

Input data and output summaries for the hydrologic and hydraulic analyses are presented in the attached Appendix B.

SECTION 6 STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual inspection. The visual inspection of Goose Creek Lake Dam indicated the dam is in fair to good condition. No evidence was noted of sinkhole development or animal burrows on the embankment. No cracking was noted, but two indistinct shallow slumps were identified on the downstream face of the embankment (Fig. A-1). These slumps appeared to be old features as the scarps or toes were not well defined. These slumps do not appear active at present, and are not considered to pose a short-term significant hazard to the stability of the dam. However, these areas should be inspected periodically to identify any renewed movement.

Erosion on the slopes of the dam was relatively minor and consisted of shallow erosion gullies. At the junction of the downstream face of the embankment with the right abutment, drainage from the abutment is confined in a ditch at the toe of the dam. Erosion of this ditch has steepened the toe of the slope and may have contributed to the shallow slumping observed in this area.

Mr McCaleb reported the crest of the dam had settled and the field survey (Fig 3-A) indicates the crest near the center of the dam is 18 to 24 in. lower than at the ends. The horizontal alignment of the dam crest appears undeformed.

The spillway was excavated by blasting in the left abutment. Erosion in this area due to flood flows is not anticipated to be significant. Some bank erosion as small scale slumping will likely occur in the downstream discharge channel, but is not anticipated to impact the stability of the dam due to the distance from the main embankment.

b. Design and construction data. No design plans or construction records were available for review. Information on the design and construction was obtained from interviews with Mr Stu McCaleb of Goose Creek Land Co. These data are summarized in Sections 1.2, 2.1, and 2.2.

Seepage and stability analyses as per the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency.

- c. <u>Operating records.</u> No operating records, water level or spillway discharge records are maintained for this facility.
- d. <u>Post construction changes</u>. Two post construction changes were reported to the inspection team by Mr McCaleb. In 1975, the spillway was deepened by about 2 ft. in order to lower the lake level.

In 1978 or 1979, 18 to 24 in. of fill was reportedly added to the dam crest. This was necessary due to gradual settlement of the embankment. The field inspection noted that the new fill appeared to be confined to the left (north) half of the embankment. The center of the crest near the maximum section still is 18 to 24 in. lower than the ends of the dam. It could not be determined if this was the result of continued settlement or incomplete repair of the settlement which had occurred prior to the remedial work.

e. <u>Seismic stability</u>. The dam is located in Seismic Zone 2, to which the guidelines assign a moderate damage potential. During a seismic event, liquifaction of the soil embankment materials is unlikely. However, without an evaluation of the static stability of the dam or knowledge of the soil properties of the embankment materials, the seismic stability cannot be evaluated.

SECTION 7 ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

a. <u>Safety.</u> Based on our visual inspection and the evaluation of available data, the dam appears to be in fair to good condition.

Two apparently shallow slumps, approximately 50 and 100 ft wide, were identified on the downstream slope of the dam, but appear to be old features and are not considered to pose a significant hazard to the dam at present. Drainage from the right abutment has eroded a gully at the junction of the embankment and right abutment, locally steepening the toe of the slope and possibly contributing to the slumping in this area. Seepage noted at the toe of the dam was insignificant at the time of the inspection.

Some settlement has occurred in the embankment. It was reported that 18 to 24-in. of fill was added to the dam crest, but the field survey shows the center of the dam is still lower than the ends of the dam crest. The horizontal alignment appears undisrupted. No evidence was noted of animal burrows or sinkhole development on the embankment. Vehicle traffic on the downstream slope has worn a path that may contribute to erosion in this area.

Hydraulic/hydrologic analysis indicate the dam will be overtopped by a flood event greater than 16 percent of the PMF. The guidelines require intermediate size dams to store and pass 100 percent of the PMF without overtopping the embankment. The analysis also indicates the reservoir and spillway will store and pass the 1 percent probability-of-occurrence flood (100 year flood) without overtopping the dam.

Seepage and stability analyses as per the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency.

b. <u>Adequacy of information</u>. The visual inspection and other information obtained for this dam provided sufficient information to support the conclusions and recommendations presented in this Phase I inspection report.

However, no design plans or as-built construction records were available for review. The geometry of the dam section, materials properties, seepage or stability analyses are not on record. This precludes a complete evaluation of the dam and is considered a deficiency which should be rectified. Seepage and stability analyses as per the guidelines should be performed by an engineer experienced in design and construction of earth dams.

- c. <u>Urgency</u>. The deficiencies described in this report could affect the safety of the dam. Remedial measures and further studies presented in Section 7.2 should be implemented without undue delay. The recommendation regarding the spillway capacity should be implemented immediately.
- d. Necessity for Phase II. In accordance with the "Recommended Guidelines for Safety Inspections of Dams," the subject investigation was a minimum study. This study revealed that additional in-depth investigations are needed to complete the assessment of the safety of the dam. Those investigations which should be performed without undue delay are described in Section 7.2b. It is our understanding from discussions with the SLD that any additional investigations are the responsibility of the owner.

7.2 Remedial Measures

- a. <u>Alternatives</u>. There are several general options which may be considered to reduce the possibility of dam failure or to diminish the harmful consequences of such a failure. Some of these general options are listed below.
 - 1. Remove the dam, or breach it to prevent storage of water.
 - 2. Increase the height of dam and/or spillway size to pass the PMF without overtopping the dam.


- 3. Purchase downstream land that would be adversely impacted by dam failure and restrict human occupancy.
- 4. Provide a highly reliable flood warning system (generally does not prevent damange but diminishes chances for loss of life).
- b. Recommendations. Based on our inspection of Goose Creek Lake Dam and evaluation of available data, it is recommended the following items be addressed without undue delay. The recommendation regarding the spillway capacity should be implemented immediately.
 - 1. Prepare a detailed hydraulic/hydrologic analysis and design a spillway and discharge channel system capable of passing 100 percent of the PMF without overtopping the dam. The spillway should be protected from erosion and/or obstruction.
 - 2. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" should be performed and made a matter of record. Such analyses should consider all appropriate loading conditions, including seismic loads, and should be made by an engineer experienced in the design and construction of earth dams.
 - 3. Erosion control measures should be designed and implemented in the area at the junction of the embankment and right abutment.
 - 4. Repair the path worn by motorcycle traffic on the downstream slope and control vehicle traffic on the embankment.
- c. O&M procedures. It is recommended that a formal program of periodic inspections and maintenance be developed and initiated at this facility. This program should be prepared by and performed under the guidance of an engineer experienced in the design, construction, and maintenance of earth dams. It should include but not be limited to the following items.
 - 1. Inspect the embankment for evidence of cracking or slumping, settlement of the dam crest, or other evidence of slope instability. These


inspections should specifically include the areas of shallow slumping noted in this Phase I inspection report (Fig. A-1).

- 2. Monitor the area of seepage near the toe of the dam to identify any changes in the amount of seepage or turbidity (soil) in the seepage water.
- 3. Remove the small trees growing on the downstream slope of the dam before they become large enough to pose a hazard to the stability of the dam. Vegetation on the dam should be maintained to the extent that it does not interfere with the inspection program.
- 4. Maintain the spillway and discharge channel free of obstructions to flood flows.
- 5. Monitor wave erosion on the upstream slope and provide erosion control measures in the event erosion becomes significant or poses a hazard to the stability of the dam.

REFERENCES


- Allgood, F. P., and Persinger, I. D., 1979, Missouri General Soil Map and Soil Association Descriptions: US Department of Agriculture, Soil Conservation Service and Missouri Agricultural Experiment Station.
- Department of the Army, Office of the Chief of Engineers, 1977, EC 1110-2-188, Engineering and Design National Program of Inspection of Non-Federal Dams.
- Department of the Army, Office of the Chief of Engineers, 1979, ER 1110-2-106, Engineering and Design National Program of Inspection of Non-Federal Dams.
- Hydrologic Engineering Center, US Army Corps of Engineers, 1978, Flood Hydrograph Package (HEC-1) Users Manual for Dam Safety Investigations.
- McCracken, M. H., 1971, Structural Features Map of Missouri: Missouri Geological Survey, scale 1:500,000.
- Missouri Geological Survey, 1979, Geologic Map of Missouri: Missouri Geological Survey, scale 1:500,000.
- St Louis District, US Army Corps of Engineers, 1979, Hydrologic/Hydraulic Standards, Phase I Safety Inspection of Non-Federal Dams.
- US Department of Agriculture, Soil Conservation Service, 1971, Hydrology: National Engineering Handbook, Section 4.
- US Department of Commerce, US Weather Bureau, 1956, Seasonal Variation of the Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Durations of 6, 12, 24 and 48 Hours, Hydrometeorological Report No. 33.






Notes:

1. Topog and Quadi





Notes:

 Topography from USGS Lawrenceton (1964) and French Village (1964) 7.5-minute Quadrangle Maps


DRAINAGE BASIN AND SITE TOPOGRAPHY


GOOSE CREEK LAKE DAM

MO. 30297

Fig. 2

١






PROFILE


PLAN AND PROFILES


GOOSE CREEK LAKE DAM


MO 30297


Fig. 3-A


















GEOLOGIC MAP


GOOSE CREEK LAKE DAM

MO 30297 Fig. 4

APPENDIX A

Photographs





Clay and silt soil with gravel to cobble and bouldersize rock fragments, used in the embankment construction.




2. Fault exposed in spillway cut. Fault dips vertically, strikes N55°W, separates white quartzite with thin soil cover on the right from dolomite with thick red-brown soil cover on the left.



3. Downstream slope of dam showing grass, weed and small tree vegetation. Note scattered boulders in embankment fill and downhill inclination of some trees. Looking south from left abutment.

4. Downstream slope and toe of dam showing cattail vegetation at toe, lush green vegetation on toe of dam, and boulders in embankment fill. Looking west, upstream.





5. View of upstream slope of dam. Note slight dip in dam crest near center. Note also rocky fill on near half of dam, apparently added to raise dam crest. High water line, far side of dam, has not become well-defined on new material. Looking south-southeast from entrance of spillway.



6. Spillway excavated at left (north) end of dam. Note remnants of concrete spillway weir in front of observer. Looking southwest from left bank of discharge channel.




7. Remnants of concrete spillway weir shown in Photo 6. Reservoir is out of picture to the right. Downstream channel flows to the left.




8. Steep rocky slopes which surround portions of the reservoir. Looking northwest from the entrance of spillway.



 Downstream discharge channel. Note small soil slumps along portions of the banks of the channel. Looking east, downstream.



10. Dam (MO 31078) under construction downstream from Goose Creek Dam. Looking west.



11. Typical contents of downstream damage zone.

APPENDIX B

Hydraulic/Hydrologic Data and Analyses

APPENDIX B Hydraulic/Hydrologic Data and Analyses

B.1 Procedures

- a. General. The hydraulic/hydrologic analyses were performed using the "HEC-1, Dam Safety Version (1 Apr 80)" computer program. The inflow hydrographs were developed for various precipitation events by applying them to a synthetic unit hydrograph. The inflow hydrographs were subsequently routed through the reservoir and appurtenant structures by the modified Puls reservoir routing option.
- b. Precipitation events. The Probable Maximum Precipitation (PMP) and the 1 and 10 percent probability-of-occurrence events were used in the analyses. The total rainfall and corresponding distributions for the 1 and 10 percent probability events were provided by the St. Louis District, Corps of Engineers. The Probable Maximum Precipitation was determined from regional curves prepared by the US Weather Bureau (Hydrometeorological Report Number 33, 1956). The Probable Maximum Precipitation distribution was computed by the HEC-1 program using standard EM-1110-1411 method.
- c. Unit hydrograph. The Soil Conservation Services (SCS) Dimensionless Unit Hydrograph method (SCS, 1971, Hydrology: National Engineering Handbook, Section 4) was used in the analysis. This method was selected because of its simplicity, applicability to drainage areas less than 10 mi², and its easy availability within the HEC-1 computer program. The total drainage basin was divided into two sub-basins, consisting of Goose Creek and a tributary drainage (Fig. 2).

The watershed lag time was computed using the SCS "curve number method" by an empirical relationship as follows:

$$L = \frac{2^{0.8}(s+1)^{0.7}}{1900 \text{ y}^{0.5}}$$
 (Equation 15-4)

where:

L = lag in hours

l = hydraulic length of the watershed in feet = 14,400 (Goose Creek); 8,400(tributary).

 $s = \frac{1000}{CN} - 10 = 4.93$

CN = hydrologic soil curve number for AMC II.

Y = average watershed land slope in percent = 5.7 (Goose Creek); 16 (tributary).

This empirical relationship accounts for the soil cover, average watershed slope and hydraulic length.

With the lag time thus computed, another empirical relationship is used to compute the time of concentration as follows:

 $T_{c} = \frac{L}{0.6}$

(Equation 15-3)

where:

 T_c = time of concentration in hours

L = lag in hours.

Subsequent to the computation of the time of concentration, the unit hydrograph duration was approximated utilizing the following relationship:

 $\Delta D = 0.133T_{C}$

(Equation 16-12)

where:

 ΔD = duration of unit excess rainfall T_C = time of concentration in hours.

The final duration was selected to provide at least three discharge ordinates prior to the peak discharge ordinate of the unit hydrograph. For this dam, the unit hydrograph duration of 10 minutes was used.

d. Infiltration losses. The infiltration losses were computed by the HEC-l computer program internally using the SCS loss function. The curve number of SCS loss rate procedure was established taking into consideration the variables of: (a) antecedent moisture condition, (b) hydrologic soil group classification, (c) vegetative cover, and (d) present land usage in the watershed. In addition, the computed basin loss was reduced proportional to the impervious area in the drainage basin.

Antecedent moisture condition III (AMC III) was used for the PMF events and AMC II was used for the 1 and 10 percent probability events, in accordance with the guidelines. The remaining variables are defined in the SCS procedure and judgements in their selection were made on the basis of visual field inspection.

- e. Starting elevations. Reservoir starting water surface elevations for this dam were set as follows:
 - (1) 1 and 10 percent probability events spillway crest elevation 744.7 ft
 - (2) Probable Maximum Storm spillway crest elevation 744.7 ft
- f. Spillway Rating Curve. The HEC-2 computer program was used to compute the spillway rating curve using discharge channel cross sections and conveyance characteristics. The HEC-2 backwater analysis indicated the control section is not at the spillway but in the discharge channel at Section E-E, Fig. 3-B, at the head of a 5-ft waterfall. Manning's "N" for spillway assumed to be 0.03.

B.2 Pertinent Data

a. <u>Drainage area.</u> 4.8 mi² (includes 3.8 mi² for Goose Creek drainage; 1.0 mi² for tributary drainage).

- b. Storm duration. A unit hydrograph was developed by the SCS method option of HEC-1 program. The design storm of 48 hours duration was divided into equal intervals equal to the unit hydrograph duration of 10 minutes (Section B.1c) in order to develop the inflow hydrograph.
- c. Lag time. 1.6 hr (Goose Creek drainage)
 .6 hr (Tributary drainage)
- d. Hydrologic soil group. B and C
- e. SCS curve numbers.
 - 1. For PMF- AMC III Curve Number 83 (for both basins)
 - For 1 and 10 percent probability-of-occurrence events AMC II Curve Number 67
- f. Storage. Elevation-area data were developed by planimetering areas at various elevation contours on the USGS Lawrenceton and French Village (1964) 7.5 minute quadrangle maps. The data were entered on the \$A and \$E cards so that the HEC-1 program could compute storage volumes.
- g. Outflow over dam crest. As the profile of the dam crest is irregular, flow over the crest was computed according to the "Flow Over Non-Level Dam Crest" supplement to the HEC-1 User's Manual. The crest length-elevation data and hydraulic constants were entered on the \$D, \$L, and \$V cards.
- h. Outflow capacity. The spillway rating curve was developed from the cross section data of the downstream channel, using the HEC-2 backwater program. The controlling section for discharge is downstream of the spillway, at Section E-E on Fig. 3-B. The results of the above were entered on the Y4 and Y5 cards of the HEC-1 program.
- i. Reservoir elevations. For the 50 and 100 percent of the PMF events, the starting reservoir elevation was 744.7 ft, the spillway crest elevation. For the 1 and 10 percent probability-of-occurrence events, the starting reservoir elevation was also 744.7 ft, the spillway crest elevation.

B.3 Results

The results of the analyses as well as the input values to the HEC-1 program follow in this Appendix. Only the results summaries are included, not the intermediate output. Complete copies of the HEC-1 output are available in the project files.

	•							-							
### 1		O HYDROGAAPH PL	ACKAGE	INEC-1	-										
2		ST REDIFICATION	•	P.R. 80											
2 42 WOODWARD-ELVOIR CONSULTANTS, HOUSTON JOB SOCZZATIOO. 5 5 1 1 2 1 2 1 1 2 1 1 1 1 1 1 1 1 1 1				009	St CHE	EK CAKE	-BAH . HAG-	3							
1 1 1 1 1 1 1 1 1 1	•	~ *	A 2		BABLE BABLE	PAKINGH		. HOUS		002241104		•	•		
			ļ = -	- ~	^										
	1 2		. ‡	-		•				•					
		• ?	* 2	8	_		HYOR	RAPH	•	-					
15		-~	-	•	\$ 6 .	102.		130.	140.	7	-83		.03		
11			* = = :	70	1.05 FL02	\$	1			-					
21		200		100	~ ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° ° °	102.		130.	Ĺ	7	•		8		
23 KI COMBINE GODSE CREEK AND TRIBUTARY FLOW 24 K 1 COMBINE GODSE CREEK AND TRIBUTARY FLOW 25 K 1 LODA ROUTING AND OVERTOPPING ANALYSIS 26 V 1 TALL TAGES TO 100.0 200.0 400.0 1500.0 2500.0 39 V 500.0 100.0 200.0 400.0 600.0 1500.0 2500.0 30 V 500.0 700.0 700.0 700.0 500.0 600.0 1500.0 2500.0 31 SE 700.0 710.0 720.0 730.0 740.0 741.7 750.0 752.3 760.0 32 SE 700.0 720.0 305.0 500.0 565.0 609.0 34 SE 700.0 720.0 720.0 760.0 760.0 760.0 752.3 760.0 35 SE 700.0 720.0 720.0 760.		0.7	~ ×		. 63	~				•					
27 K 1 DAM 28 K 1 1 DAM 29 V 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		4.6	=	15		1	ANO	RIBUTAR	Y FLOW						
27 V1 1 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2			¥ ;				ONCORO	D 7 at 6 at	313811	-					
29	A A R	9~				•				7.44.7	7	,			
32		· • •	\$ \$ \$		50.0	100.0	200	6.00.	1	9000	1500.0	2500.0	4000.0		
33 SE 700.0 710.0 720.0 740.0 741.7 750.0 752.3 35 SD 752.3 2.0 1.5 36 SL 752.3 755.0 385.0 565.0 669.0 36 N 99 755.3 754.6 754.6 756.6		1	**		7.0	16.0	36.	0.84		9.8.0	108.	149.0			
34 K 99.0 38.0 38.0 50.0 565.0 38.0 500.0 565.0 38.0 500.0 565.0 38.0 500.0 565.0 56	A B	E1	SE 70		2001	720.0	730.	740.0		0.067	752.3	760.0			
34 K 99 753.3 753.2 754.6 754.6		5.0	-	m •	205.0		\$00.	565.0							
			*	Í	7534		4444	754.8	- 456vB-					B4	Inpu Vari Goos MO B4
	-														t Dat ous l se Cre 3029
															ta PMF E eek L
													-		vents ake Da
															ım


<u> </u>	<u> </u>	• 3 : 3	1111	222	<u> </u>	****	<u> </u>	7777	2711	<u> </u>	YIIY	<u> </u>	211	<u> </u>	1111	ш	1111	222	
																Outr Vari	out Si ous	ummar PMF E eek L	y vents ake Dam
CKAO	-BAR-SAFETY VERSTUN JULY 1979 - LAST MODIFICATION OL APR 80 	AUN DATE? 41/05/27. TIME? 12.30.45.		GOUSE CREEK LAKE BAM NO. 30297 WOODWARD-CLYDE CONSULTARTS. MOUSTON JOB 80C224T100. PROBABLE HAXIMUM FLODD ANALYSIS (PMF)	NO NHR NMIN TOAY THR IMIN METRC TPLT IPRT NSTAN	JOPER NUT LROPT TRACE 5 0	MULTI-PLAM ANALYSES TO BE PERFORMED	A7105 .50 1.00	***************************************		SOUSE CREEK INCLOV HYDROGRAPH ISTAO ICOMP IECON ITAPE JPLT JPRT IMAME ISTAGE 18UTO	HYDROGRAPH DATA	1 2 3.78 1.00 0.000 0 0 0 0 0 0 0	SPFE PMS R6 R12 R24 R48 R72 R96 0.00 0.00 26.00 102.00 120.00 130.00 140.00 0.00	LOSS DATA LROFT STRKE DLTKR RTIGL ERAIN STRKS RTIDK STRTL CNSTL ALSMX RTIMP 1.00 -1.00 -1.00 0.00	-63.00 WETNESS = -1.00 EFFECT CN = 83.00	UNIT HYDROGRAPH DATA TC= 0.00 LAG= 1.60	RECESSION DATA STRTG= -1.00 QRCSN05 RTIOR= 5.00	JUNIT HYDROGRAPH 50 ENU OF PERIOD ORDINATES, TC* 0.00 HOURS, LAG* 1.60 VOLT 1.00 12. 107. 203. 331. 501. 753. 629. 517. 436. 370. 314. 272. 233. 199. 167. 143. 122. 104. 88. 75. 63. 24. 46. 39. 33. 29. 24. 21. 17. 15. 13. 11. 10. 9. 7. 6. 5. 4. 3.
		١.,			<u></u>	<u> </u>	<u> </u>	1	1	١,,,,		<u> </u>	1						

																																۷a		Ou	is Cr	PM ee	۱F	E١	/er			n			
COMP O	63	52.	£2.	76.	113.		# 56.	100	219.	235.	264	274.	285	.E.62	102	312.	317.	322-	329.	132.	334.	337.	341.	343.	366	347.	349	363.	282	457	520	548.	284	662.	981.	1162	1243.	49467	1376.	1428.	1511.	1546.	1636	1626	1626.
1.	10.	10.	٠٥٠	100		4	10.	10.	.01	.0.	5		101			60.	60.	8 8		8	60.	9	00	00.	8 6	00.	00	20.	3	70.	10	5	.01	10.	5.	3 5	56	4	10:	10.	10.	.01	3 6		-0-
57.	20.	20.	20.	20.	20.	20	20.	.02	-05	-05	2 2	.92	-05	20.	20	- 02	- 05	200	20.	05	-05	20.	-05	20.	200	. 02	05	::	1:	==	21-	~1:	-12	-15	~:	~~	71.	4	~:	21.	21.	115	2 2	~ ~	115
3. RAIN	•03	60.	• 03	60	0.00	5	• 03	60.	603	• 03	6	6	-03	.03	6	.03	•03	603		03	60.		60.	•03		60.	603	£1.	= :	3.5	13	£:	.13	.13	٤١٠		.13	=======================================	£1:	-	.13	.13			.13
1E R 1.00	146	891	671	- 150	121	1	154	155	151	158	94	191	-162	163	34	991	167	168	1 70	127	172	173	175	176	- N	179	180	182	183	185	186	197	188	190	161	- 761	194	105	196	7 60 1	661	200	200	202	203
4. HR . HN . 1	• 20	Ĉ.	.50	00.1	1.20	1.30	1.40	2.00	2.10	2.20	07.7	2.50	3.00	3.10	36.5	3.40	3.50	00.4	02.	96	9.	000	5.10	5.20	9 6	5.50	00.9	02.9	6.30	5.00	7.00	01.	2.30	7.40	7.50	200.4	9.20	96.4	8.40	000	9.6	07.6	96.0		9.50
5. FLOW MO.0A	1.02	1.02	1.02	201	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	70.1	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	7071	1.02	1.02	1.02	70-1	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	100	1.02	1.02	1.02	1.02	7.07	7 0 7	1.02
6. NO-OF-PERIOD	٠ مم	·~	?	?	; .:		-	•	: :	:		: :	-	: .	: .	: _:			: -:		.	• 	• •	:		: -	1.	::	•	: .:		: ,	• ,	2.	.		, _c	3.	Å,	• •		;		•	•
Fr Er	00.	00.	00.	90	200	8	00.	900	8	00.	9 6	80.	90	8	9	6.	06.	00		8	00.	3	00	00.	9 6	60.	00	10.	100	10	10	ē.	10.	10.	10.	10		4	٥٠ •	16.	10	10.	10	. .	70.
excs	60.	30	20.	3 8	3 8	00	00	90.	3	60.	9 9	8	8	ē 8	3	8	00.	3 3	33	3	0.	3 5	80	.03	8	9.	36	8	3 8	5 5	00	80.	3 8	8	00.	3 5	38.	3	80.	2 5	60	.00	90		S.
RAIN	00.	00	00.	9	9 9		00.	00.	00	00.	9 9	00.	00	3.5	3	0	• 00	300	200	3	000	9 6	00	00.	90	00.	000	10.	1	5 6	3	~ ·		5	10:	3 6		*	3 :	: : :		10.	10		10.
10.	~	-	•		~ ه	. 🕴	•	01	~	S :	=	: ≏	7	≘ :		: =	~		5 %	*	27	9 6	2	31	=======================================	*	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	2 %		7 0		?:	7	ţ	9 .	***	•	*	3	7.5	. 5	55	2 2	* *	2
11.	01.	2	04.	-	3 -		1.30	0 4	00.	2.10	95.	2.40	94.4	3.00		3.30	3.40			*	4.30		69.	5.10	9	5.40	966	9:0			2.2	. O.		7.30	0	20.2	6.10	2.4	9.30		30.0	01.6	200	•	•
0	1.02	10.	1.01	100	10.1		101	70.7	1001	10.1	4 5	10:1	100	707		101	1.01		10.1		10.1	10.1	16.1	1.01	-	10-1	700	10-1	1	10.1		70.1	3	10.1	1001	101	1001	10.4	16.1	10.1	1.0	10.1	10.1	0	10.I

77		1		PC	<u> </u>	7	: :	<u> </u>	Ą							•	Œ	~ ^	÷	<u></u>		7	·	: <u>?</u>	2 3	<u>,</u>	<u> </u>	<u> </u>	<u> </u>	1	<u>a :</u>	*	K 8	Ξ.		X 5	3	7 X	A	Ţă	X I		<u> </u>	7_	1 2 8	Ţ	<u> </u>			<u> </u>	<u> </u>	1.3	<u> </u>	1 7.
																																							V	00 0	io se	us	i l	PM Pe	F	E١	y ver a ke			m 1				
662.	1074	1162.	1243.	1376.	1428.	1472	1511.	1546.		1626.	1647	S	1061.	1696.	1 700.	1724	1340	1748.	7984	1763.	1769.	1300		1001	1997.	2152.	2368	2639.	2994.		3000	000	4791.	5149.	6060	6163.	6484	6 800.	7116.	2460	100	9522	10557.	11771.	13063	.61141	14963.	15555	15470.	12.45	14639.	14034.	13256.	11624.
10.	10*	10.	10.	5	10.	10.	10.				0.	10.	10.	10.	- O	10.0	10	5	10.	٠.	10.	100	· ·	30.	10.	10.	18.	10.	٠٥٠			10	10.	.01	1 2	5 6	10	10.	10.	 	ĵ.		00.	00.	60	00.	00.	5 6	00.	8	00.	00.	00.	, 0
21.	-12	-15	-12	~	.12	- 12	•12	21.		21.	77.	-15	-12	21.	21.	71.	-	?		~1.	-15	Į;	7			64	-63-	• 52	545	:				• 65		9	99.	. 60	1.00				.62	79.	24.	24.	24.		-	*	4	.	4.	
.13		.13	£13	1	.13		=	,	=	3 =		=	.13	.13	:	= :			7	.13	•13	:			*	4	**	.53	.53			. 4	99.	• 66	4	99	99.	09.	10.1				29	79.	4	29.	79.	700	64	4	•	64.	0.40	
161	761	193	761	1961	197	198	661	200		202	204	205	206	207	208	662		212	1	514	215	2	717	977	220	122	-225	223	524	\$:	227	300	523	230		233	234	235	236		236	2 40	₹	242	*	**	245	747	848	642	250	152	- 252	254
7.50	00.	8.10	9.20	8.40	8.50	90.6	9.10	9.20	3		10.00	10.10	10.20	10.30	10.40	06.01		11.20	44.30	11.40	11.50	12.00	17.10	22.27	12.40	12.50	-1.3.00-	13.10	13,20	P. C.	0 5 6 1	7.50	14.10	14.20	07.4	14.50	8 67	15.10	15.20	12.5	15.40	100-00	16.10	16.20	16436	16.40	16.50	17,10	17.20	17.30	17.40	17.50	6.63	18.20
1.02	1.02	1.02	1.02	70.1	1.02	1.02	1.02	1.02	2	1.02	1.02	1.02	1.02	1.02	1.02	70.1		1.02	70.7	1.02	1.02	1.02	70.1	100	1.02	1.02	1.92	1.02	1.02	200	1.02	20-1	1.02	1.02		1.02	1.02	1.02	1.02	1.05	1.02	1 02	1.02	1.02	1402	1.02	20•1	1.02	1.02	1.02	1.02	1.02	70.1	1.02
· • •		.	، ئىم			*	;	÷.	•	; ;	; ;	;	•	÷	;	; .		; ;	-	;	;	*	÷	,				11.	15.	•	33.		52.	63.		103.	118	134.	152.	-627	141.	797	304.	367.	435	504	575.	554.	696.	647.	694.	694.	667.	611.
. 6.	16	16.	16.	10.	16.	10.	10.	٠ •	1		16.	10.	10.	16.	10.	10.	10	10.	4	10.	10.	40	5.6		.03	.03	493	.03	.03		5.5		.03	.03	6	56	60	.03	20.	*	000		.02	10.	16.	10.	10.	16.	10.	162	10.	10.	10.	00.
333	3	3.	8	8	90.	8	60	3	3 8	2 6	3	8	00.	9	9	3	3 6	3	3	90•	00.	26	3 8	3 8	80	70.	10	10.	10.		•	6	6.	70.	200	200	70	20.	70.	3 3	80.	101	*0	.03	6	.03	٠ و د	60	60.	- (0)	• 03	•03		Ę
700	7	70.	10.	3.	77.	100	٠٠.	~ 0,	3	į (70.	10.	10.	70.	<u>و</u>	1	5	1	10.	10.	3	10.	5	60	.0	.63	•03	0	3 3			0	50.		50,	40.	•00	\$0.				•0•	•00	\$	\$0°	50.	50.	3	0	•	\$ 0°	* 5	0 2
. 4 4	- 64	20	5	3	?\$	- 53	24	55		C 4		09	19	62	63	•		200	\$	5	2		77	2	25	2	-11	78	5		1 0 8	20	*	82	\$:	. 60	-	9	16	4	7 6	\$	96	44		66	100	102	103	***	105	901	108	103
7.30	0,0	00.0	9.10	0.10	04.0	9436	9.00	9.10	۲ ٔ		7	10.01	10.1	2	19.30	2							12.00	01.21	12,30	12.40	42.54	13.00	13.10		13.50		14.00	01.41		04-41	04.4	15.00	15.10	₹:	06.61		16.00	10.10	16520	16.30	16.40	17.00	17.10	17:23	17.30	17.40	14.00	14.10
	1001	1.01	10.1	6	10.1	1001	10.1	10.1		3	10-1	10.1	10.1	10.1	1.01	10.1	-	10.1	4	10.1	10.1		7.07		10.1	10.1	10.1	10.1	10.1		100		10.1	1.01		1011	1	10.1	10.1				1.01	10.1		10.1	10:1	10.1	1001	10:1	10.1	10.1	10.1	
3			•		4			-								-					·					.		x 1					•					.					-	· · ·		*		3	· ·		r	-		Τ-
				-	_				- 1	۴,		•				7				•			7		•	7		,)		7	_		, –	_	7)))))

1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,																																				٧a	ari oos O	ou e	s P	imma MF eek	E١	ve	nt: e	s Da	m			
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	13296.	12446.	11624.	10260	9050			~ .	5915	5143.	4526.	3968.	3457	2663.	2354.	2104.	1.966.	1071	14041	1286.	1188.	1105.	1935.	923.	878.	639	865	240	726.	706.	676.	•	492643.						•		į		. •		• (•	•
1.00	000	00	66	6		-00	00.	00.	00	5	-60*	60.		60.	6.	6.	8	6.6	9 6	00.	g	8	6	8	00.	00*		9	00.	9	0.00	00.0	5.5									-	. 0]	~ ~	? :	2	67
1.	64.	•	•	ć	6	• 0 •	*	0	0	46.	94	*0.		ć	46.	*6.	•	4 6		•	-04	\$	•	ò	•0	*0	• •		•0•	0			34.12									-		ļ,	: :	; 	~ ;	59.
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	54.	•	•	3 6	Š	+U*	**	.		8	+0.	5		ć	•0•	÷.	5	6		6	40	6	6	0	0	00	5 6		0	6	000	•	36.40	GME	64.	99.	6-60	65.			-		•	 -	 	2.	•	
1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1, 1,	252	253	254	75.	257	- 558	259	260	767	263	564	592	242	268	692	270	142	272	7.7	275	778	277	270	580	1 82	282	284	782	286	287	29.9	240	NON	4	4923	33	S.	93			ļ					;		
1.1.10	6.6	19.10	18.20	18.60	18.50	-16°00-	01.61	19.20	09-01	19.50	06.02-	20.10	02.02	20.40	20.50	21.00	21.10	21.20	21.40	21.50	22.00	22.10	02.22	22.40	22.50	-53.00-	23.10	200	23.40	23.50	01.	.20		Ì		99	66	55.			-	-	· &			?	•	;
12.56	1.02	1.02	1.02	200	1.02	- 1.02 -	1.02	1.02	20.	1.02	-1.02-	70.1	20.1	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	20.1	1.02	1.02	1.02	70.	2	1.02	1.02	1.03	1.03		72		33,	854	83			Z T			ا ا			~	^
11.10	· · · · · · · · · · · · · · · · · · ·	٠.	: ئـ				*	• •		• 0			•		5.	٠.	· 5•	•	ř	3.	7	7.	•	, ,	3.	·	• •			٠. د	•	•		24-H0UR	3302.	S	7.65	8080			101		•				.	31.
19.00 108	:					:								_	_	-	-	-																10	12	9 07	99.2				<u> </u>			.	<u>.</u>	:	.	•
15.50 108	:																																	EAK	55.					:	•		•					~
14.00 108 118 119 119 119 119 119 119 119 119 11	0.	ē	8	•	Š	(5·	.00	8	3 2		60.	90	200	99	• 00	•	3	3.8	9	3	3	8	00.	8	00.	00	00.	3	8	9	0	• 05		•	155			-			1 1 L	<u>.</u>	•	٥.	- - -	; *	? ;	٠١٦
111 00 111 00 111 111 111 111 111 111 1	+3.	40.	000		9	90.	00.	000		000	90.	60.	30.	3	.00	00.	00.	9		9	9	000	000	0	00•	00	3 6		00	9	3	.03			CF.S	I NCHE S	E	နှ ပ							• •			
		807 1	601		111	113	+17	115	=======================================	118	1	120	121	123	124	125	921	121	120	130	=======================================	132	133	135	1 36	137	138		1+1	741		•				_		THOU	·					-	- ~		~ :	17.
	17.50	14.00	01.61	19:40	?		14.00	61.61		•	12.50	20.00	01.02	20.30	20.40	20.50	21.00	21.10	92.12	21.40	21.50	22.00	22.30	22,30	22.40	***	23.10		23.30	23.40	00.0	21.										; - :	: ,	-	: :	*	∴ :	٢3.
		10.1	10.1		10.1	10.1	1.01	1.61		10:1	1	70	10	10	70	5					- 1		- 1	1								1.02																

					•		- 2 2										Ou Va	tpu ric ose	it S ous Cr 3029	PM eel	nar F E	y ven	ts		
											-	CONT G	Ž	,	:43	żż	2:	:	22			- 1	= 1	÷:	; ;
:		0.0								.99		1055	55.		5.5	56	10.	.01	5.5	1	55	10.	00	9	. 00
••••••		F IAUT		9636		R T THP				104.		excs	70.	*	20.	70.	õ	20.	20.	2	20.	20.	20.	20.	70.
-		ISTAGE		**************************************	* 8	ALSMX 0.00				36.	·	RAIN	60.0		66	566	9 5	.03	9.0	100	50	60.	6.5	9	5 6
•		IMANE		St news	2. 0.00 0.00	CNSTL 83.00			00	LAG-		PER 100	747		151	153	156	157	159	3	(9)	- 591 	997	166	
•••••		2887		T	8 R72 0 0.00	STRTL -1.00	_		R 7108- 5.00	.00 HDURS. 355.		1	30	2	8019	1.30	2.00	2-10	2.30	2.50	01.6	3.30	3.40	00.4	
İ	COMPUTATION	JPLT		000000	R48 140.00	110k	# E	DATA .63	.05	526.		MO.0M	70:1	20.1	20.1	1.02	1.02	1.02	1.02	200	1.02	70.1	20.7	1.02	1.02
•	RUNGFF	CON ITAPE		1.00	PRECIP DATA RL2 R24 20.00 130.00	LOSS DATA STRKS R 0.00	1.00 EFFECT	HYDROGRAPH LAG=	RECESSION DAT	ORDINATES. TC		CONP Q		:		.00	0	.00	••	•	• • •	• 0	• 0	•	•
:	20	100MP 16C	7	00.0	R6 102-90 12	L ERAÍN D 0 00	. 55	10.0 -21	-1.00	PERI 00 672.		7055	000		000	000	00.	99	000	9 6	38	000	00.0	60.	3 3
•		1		1.00	PMS 26.00 1	R RT10L	_		STR14.	1 END OF		EXCS	30.	3	\$ 8 8	983	00	90.	000	9	000	86	200	8.0	3
		ISTAD		1010	SPFE 0.00	DL74R 0.00				~ ~		RAIN	900		99	000	00.	00.	000	000	000	000	00.	00.	30
:				1		S TRKR 0.00	CURVE NO			£~	:	PER 1 00	~~	•	v • 1	••	==	27	: ::	=======================================		02	≂ \$	23	5.5
						14007	3			UNIT	-	MR. MM	07.		1.00	02:1	05:-	2.00	2.20	9	00.6	3.20	2.30	3.50	91.4
-												MO.0M	1.01		10.1	55.	10:1	10.1	10.1	10.1		10:1	10.1	10.1	1001
	<u>.</u>	111	4 1							7 . 7	1 1 2										Z ∷x	1			1



201 1.02 94. 1.02 95. 1.02 95. 1.02 257. 1.02 257. 1.02 264. 1.02 264. 1.02 272. 1.02 273. 1.02 274. 1.02 275. 1.02 275. 1.02 276. 1.03 277. 1.03 277. 1.03 277. 1.03 278. 1.03 279.				
257. 257. 257. 257. 257. 264. 264. 264. 264. 264. 264. 264. 264		222000000000000000000000000000000000000		
29.5. 29.2. 29.2. 29.2. 20.2. 20.3. 20.4.	202222222222222222222222222222222222222			
25.7. 25.7. 25.7. 26.4. 26.4. 26.4. 26.4. 27.7. 26.4. 27.7. 26.4. 27.7. 26.4. 27.7. 26.4. 27.7. 26.4. 27.7. 26.4. 27.7. 26.4.	100000000000000000000000000000000000000			
257. 257. 257. 202. 204. 264. 194. 175. 180.	160000000000000000000000000000000000000			
267. 202. 202. 204. 204. 104. 104. 150.				
292. 264. 264. 194. 175. 176. 176.				
264. 264. 194. 175. 176. 180.				
194. 175. 180. 150.				
175. 150. 140.				
150.				
140.	160000000000000000000000000000000000000			
	110000000			
124.	1000000			
119.	22222		866886888888888888888888888888888888888	
114.	2222			
• 68	000		56688668	
20.	00		8 6 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	
53.	9	1 1	888888888888888888888888888888888888888	
34.	g		90 90 90 90 90 90 90 90	60 00 00 00 00 00 00 00 00 00 00 00 00 0
23.		1	96.69	
19.	0		000	000
14.			60.	60. 00.
13.			***	000
11.	0		60.	00
11.	0		00.	
10.	-		00	00.
10.	2 :		00.	00.
10.	3 8		90	00.
.01	000		00	00.
10	2 8		3	131
	20		0	132 000 000
10.	8		90	133 .00 .00
10.	2		90.	134 .00
10.	2 9	İ	000	00.
10.			00	00. 00. 761
10.	0			138 .00 .00
10.	١,		00	00 00 001
• •			60	
	1		8	00 241
10.			00.	143 .00 .00
10.	_		00.	00. 00. ++1
	-	1	70.	70.

-	PEAK FLOW	AND STORAG	CEND OF	F PERTOD! CUBIC FEE 1EA IN SQU	E CEND OF PERIODS SUMMARY FOR MULTIP FLOWS IN CUBIC FEET PER SECOND (CUBI	MMARY FOR MULTIPLE PLAM-RATIC PER SECOND (CUBIC METERS PER E MILES (SQUARE KILDMETERS)	C HETERS PER SE	SECONDNIC COL	COMPUTATIONS		
					•	800	200 12 CA C2+ 1884 201440				
UPERA TION	STATEON	4864	PLAN	RAF10 1	4AT10 2 1.00						
HYDKOGRAPH A	AT EMFLUS	3.78	-	220.2414	15555.						
HTOROGRAPH A	AT INFLOS	1.00	~	3203.	181-4216						
2 COMBINED	INFLOW	4.78	-+	9423.	19947.						
ROUTED TO	DAM	4.78	-	9161.	18619. \$27.2414	And at the second secon		To come the endpoint of the property of the pr			
	PLAN 1			And the same of th	INITIAL VALUE	VALUE	SPILLHAY CREST	ST TOP	OF DAM		
			51	ELEVATION Stuarge Outflor	744.70 1220. 9.	44.70 1220. 9.	744.70 		752.30 1923. 1981.		
		RATIO OF PMF	MA) RESE	MAXINUM RESERVOIR W. S. ELEW	MAKIAUM DEPTH GVER-BAM	MAXINUM STORAGE	MAXINUM OUTFLOW CFS	DURATION DVER TOP HDURS	TIME OF MAX GUTFLOW HOURS	TIME OF FAILURE HOURS	
		.50		755.62	3.32	2308.	9161.	7.00	41.33	0.00	Output Various Goose C MO 302 B12
											PMF Ever
				:		1					nts e D

										Vari	.ous	Summary PMF Event reek Lake 97
									TIME OF FAILURE HOURS	00.0	00.0	000
ECONDHIC COMPUTATIONS ECONDI							DF DAM 752.30	1681.	TIME OF MAX OUTFLOW HOURS	42.63	42.67	49.54
	.045 RATIO 5	2900.	1153.	3392.	2102.	4.7515	109		DURATION OVER TOP HOURS	0.09	00.0	2.00
Y FOR MULTIPLE PLAN-RATIO SECOND (CUBIC METERS PER LES-150VARE KILUMETERS)	RATIOS APPLIED TO FLOWS RATIO 3 RATIO 4 RAT .16 .17	2644.	1089.	3204.	1945.	DAM SAFETY ANALYSIS	SPILLWAY CREST 744.70	0	HAX INUM OUTFLOW CFS	1513.	1804.	- 2102
SUMMARY FOR MULTIPLE PLAN-RAT I PER SECOND (CUBIC METERS PE NAVE-MILES-(SOUARE-KILUMETERS)	RATIOS 4	2489.	1025.	3015.	1804.	SUMMARY OF DAM	J.	•	MAXIMUM STORAGE AC-FT	1841.	1905.	1967
SUMMAR T PER	RATIO 2	2333. 166.83H	961.	2827.	1661.	Wns.	INITIAL VAL		MAXINUM DEPTH GVEG DAM	0.00	0.00	
FLOWS IN CUBIC FEE	PLAN RATIO 1	1 2178.	1 897.	1 2639.	1 1513.		ELEVATION	OUTFLOW	MAXINUM RESERVOIR	751.53	752.14	H 7754
AND STORAGE (END FLOMS	AREA	3.78	1.00	4.78	4.78				RATIO OF R		91.	
PEAK FLOW	STATEON	IMFLUI	INFL32	INFLOW	HVO		1					
	OPERATION .	HYDROGRAPH AT	HYDLOGRAPH AT	2 CUMBINED	KOUTED TO		PLAN					

ener O

7-

ċ

	PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FLOOD TO PROBABLLISTIC FOR TO PROBABLISTIC FOR TO	LYDE CONSULTIC FLOOD 11C FLOOD 11C FLOOD 100 100 100 100 100 100 100	# MB. 3024 ULTANTS. H 100-YEAR 100-YEAR 100 100 100 100 100 100 100 100 100 10	1.50 1.50 1.50 100 010 010 010 010	JOB 80C224TL00						
24	MODDWARD-C MODDWARD-C PROBABILIS PROBABILIS 1 NFL DOI 0 010 010 010 010 010 010 010 010 010	LYDE CONS LYDE CONS TIC FLOOD 3.78 3.78 3.78 9.010 9.010 9.010	100-YEAR 100	1.50 1.50 1.50 1.50 1.50 1.50 1.50 1.50							
10	1NFL01 6085E-CREE 8.881 .010 .010 .010 .010 .010 .010	3.78 % 3.	010 010 010 010 010 010 010 010 010	010 010 010 010 010 010		41100.					
862	8.881 0100 0100 0100 0100 0100 0100 0100	010000000000000000000000000000000000000		1.50 010 010 010 010 010 010	,	-	•				
		010	1 1 1		0.1						
555555555555555555555555555555555555555			010.010.010.010.010.010.010.010.010.010		919	919	919	919	919		
5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		010	010					016.	010		
555555555555555555555555555555555555555		010000000000000000000000000000000000000	010.					916	010		
3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5		010	010.	1				010	.010		
		010	010 010 910			l		910	010		
3 3 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6		010	010.					010	010		
		010	010.					010	610.		
		010	,,,,					010	010		
			010.					010	010		
		010	610.	1				414	616.		
		010	010					016	010.		
		100				0.0		9 0	100		
		\$10 .	110.					*10	*10 *		
		*10 *	*10.					.014	+10.		
		20.	820.					679	0.45	4	
10000	920.	870.	970.		. 820.	920		.028	.028 .028		
		456.	920		İ			050	0.50		
		040.	.	.050	•	790		, ii.	£1.		
1000	0070	2020	1 640.	950	•	-		9 9	.11.		
10		*10	•10.		• •			10	410·		
10			.016	•	•	*10		•10·	*10.		
•		ФС	9 9	110				+10	*010*		1 G
		-		•	•	77	19-		•03	0 14	npu % P oos
[- X	- 60									30	ro e
. 8	INFLO2	•								29	ba Cr
4	FRIBUTANY		1	HY DROGRAPH	1						bi ee
892- 0 54		:			> ·						
6.7	1					+			600	-	
		æ									
7						; ; =					

وحور

E	13												
	25	* * * * * * * * * * * * * * * * * * *	L DAM FLOOD ROUTING	TING AND	DVEOTOR			-					
-	*				- Carrier	SISATURE THE ANALYSIS	LVS1S						
1	\$ \$ 3	7. 244.7	746.1	7.66.5	747.2	748.1	749.0	7.44.7	1-1-27	1 2			
		V5 0.000.0	20.0	100.0	200.0	400.0	0.009	0.000	ı	2500.0	4000-0		ı
	000	\$E 700.0 \$\$744.7	710.0	720.0	730.0	740.0	741.7	750.0	ſ	760.0			
4	235	\$L 0. \$V 752.3	205.0	385.0	500.0	565.0	756.8						,
	;												
											,		1
À L.													1
													,
													-
CI.													1
													
						1							,
													<u> </u>
													1111
1											B15	Inpi	ÎZXX
												robal Probal Se Cre 3029	
												ta bilit ek L	
1						:			:			v Eve	-
												an	

LAKE DAM MD. 10297 LYDE CJNSULTANTS. HDUSTON TIC FLOOD 100-YEAR TIC FLOOD 100-YEAR TIC FLOOD 100-YEAR HIN IDAY IHAR IN AND SPECIFIC SUB-AREA RUNDFF C O	
	COUSE CREE COUSE

10. 10. 10.	.03			21.	.05	101				1	1	*	T M	4-	T							ļ	B17	7		1		1				
10.	.03			21.	e d	5						. 1	nue.		الله والمالية المنابعة المنابعة ال	0 4400	ž	24.	- 92 - 92	ż	90.	330	3 %. 36.	30	• 0	25.	43.		*		0	
		66	.05				.01		3				1.00	314.	i :	LOSS	10.	10.	10.	5	5	-	ē.		55	10.	.01	10.	.01	10.	5.	•
				. 12	ž.	16.	10.		EO.				1	379.	~	EXCS	e.	.00	60.	000	000	06	000	88		60.	. 99	66.	.00		60.	. 99
	6	56	• 05	21.	•05	10.	10.	124	0.00 0.00				1.60	436. 88.	· ·	R 4 1.1		10.	10.	16.	5.5	10.	5.5.	100	50.	10.	5.	10.	10.		· 6	10.
									-67.00				\$.			P ER 100		148	150	2 2	153	-451	156	941	0 91	191	163	165	991	198	691	947
16.	.03	60	.05	\$ ~ ·	\$0.	16.	.01		5 TR TL -1.00	•	Andread State - the Control		**************************************	\$17. 517. 104.	÷	HR.MN	30	* 4	1.00	7.50	1.30	7.1	2.09 2.10	2.30	2.40	3.00	3.10	3.30	3.40	4.00	01.4	4.20
5 5 5	60.	9 6	60	.53	•0•	10.	10.	2	A 7 10K		H DATA	-	°	628. 122.		HO.DA	70.1	1.02	20.1	30.7	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	70.1	1.02	20.1
10.	6.0	60	60.	1.36	.05	10.	10.	LUSS DATA	NSTRKS	-1.09 - EFFEE	HYDROCRAP	LECES \$ 10M	BRESN- ROINATES.	753.		0-01-PERIOD COMP 0		2.	• · ·	• • • • • • • • • • • • • • • • • • • •		3.	. "	-		•	.	• •	•		•	;;
70.0	60.	, e	6	\$9.	•0•	10.	10.		FRA!	*	16.0.040		PER 100	856. 167.		¥, SS07	16.	10.	10.	10.	5.0	10.		16.	55	16.	6.	16.	10.	16.	; ē.	16.
56	.03	60	.03	£2:	.07	10.	.01		*	I			STREB.	942.		EXCS	80.	00.	00	68	000	96	88	96.	6	38.	60.	\$ 3.	00.	3 7	00.	90.
									0.00	1			GRAPH			RAIN	10.	10.	200	7	6.	5.0		20		10.	6	10.	10.	2 2	2.	10.
3 3	£0.		5	87°	70.	10.	10.		\$ 184.K	CURVE NO			UNIT HYDRO	1016.	0.7	PER 100	-		· • •	•	• •	-	17	=======================================	15	17	2	22	12	23	.	22
5	.03	50	.03	21.	.07	10.	10.						2 2	1075.		#K. ##	07.	30		3 2	1.20		2.00	61.7	7.30	1000 2000 2000	3.00	1.20	3,30	1.50	••00	02:
																MQ.0A	1:01	101	55.		10.1	1021	10.1	10,1	• •	10:1	10.1	10.1	10.1	70.1	1001	10.7

l			1			l									}			,			_	_	Γ				<u>-</u> f	Ť	<u>. n</u>	<u>2 </u>	R .	-		R ;		<u> </u>	2 2	<u>, , , , , , , , , , , , , , , , , , , </u>	9.6	1	7 7	T		; ;		X 3	Î	<u> </u>	3 3	2		T		
																									!		•															P	ro e	Ъa	bi ee	11:	Ĺt	у	Ev			i		
•	•06	, ,	45.	53.	54.			\$6.	. i	2.5	5.0	• 0	• .			: ;		87.	• • •	100	106.	112.			128.	137.	141.	***	149.	151	157	159.	- 201	167	110	172.	174.	179.	101	18.5	187.	191-	195.	201-	218-	231.	447	259.	2 74.	308	326.	27.5	2.2	
5	٠ •	٠٥.	10.	10.	10.	10.	٠٥.	.01	10.	10.	-05	20.	20.	20.	70	200	905	- 02	-05	50.	• 02	-05	3	20.	, 0 ¢	102	- 02	-05	20.	20.	20.	• 0 •	263) -	0.	10.	10.	10.	.01		. 02	-03	.02	20.	20	.00	-03	20.	٠٥,	.03	50.	90		
	.00	66.	. 60	.00	•0•	66.	•	•0•	00.	00.	.01	10.	10.	10.	10			16.	5	-100	٤.	٤٠;		6.	10.	10.	16.	10.	ē:	50.5	10.	10.	46	5 5	-10+	10.	10.	10.	16.	5	6	60	.03	.00	60		-03	.03	0.	ć	.07	200		
	16.	10.		10.	16.		10.	.01	10.	10.	.03	60.	• 03	.00	6	3 6		6.	03	40.	.03	6		5		.03	.03	2	6.6	5 6	.03	.03	6		6	60.	.03	.03	6.		.05	500	• 05	ė,	.05	.05	-05	5.5	.02	20.	21.	27	70.	-
	7	172	173	174	175	136	177	178	1 79	0.81	191	281	143	4 91		0 4	186	189	190	101	761	193	1		961	198	199	299	201 201	707	204	205	2	208	502	210	112	213	214	716	212	***	612	022	727	223	727	225	727	822	622	230		
,	4.30	4.40	4.50	5.00	5.10	5.20	5.30	5.40	5.50	00.9	01.9	07.9	9.30	0,0	1.00		7 20	7.30	7.40	7.50-	8.00	8.10		0,00	9 4	00.6	01.6	926	6. 6.	2 0	10.00	10.10	\$ 5 6 7	00.00	-10.50	00.11	11.10	11.30	11.40	12.00	12.10	12.20	12.30	12.40	13.00	13.10	1320	13,30	13.50	14.00	01.11	14.30	000	-
	70.1	1.02	1.02	1.02	1.02	20-7	1.02	1.02	1.02	1.02	1.02	1.02	20.1	20.1	70.4	70.1	1.02	1.02	1.02	1.02	1.02	1.02	3	70.1	20.1	1.02	1.02	1.02	1.02	7001	1.02	1.02	20.1	1.02	1.02	1.02	1.02	1.02	1.02	70.1	1.02	1.02	1.02	1.02	1.02	1.02	1-03	1.02	1.02	1.02	1.02	20.7	70.1	V V
	<i>:</i>	;		;	;	•	;	÷	;	÷	;	; .	;	; ,	•	: .	•		: ;		;	;	•	; ,	•		;		; .	•	;	•		,		; .	•	* 4	; .			•	•	<i>:</i> .	***		-	•			•	•	: .	•
	16.		10*	10.	16.	16.	10.	10.	10.	16.	10.	10.	10.	10.	100	7.		16	10.	16.	10.	10.	160	.	10.	10.	.01	1		10.	.01	10.	10	100	10.	10.	.91	.01	.91	100	10.	70.	10.	10.	10	16.	10.	10.	10.	10.	7.	10.		=
3	00.	0	90.	90.	00.	26.	8.	00.	60.	••0	3	00.	00.	6	3 5	9	8	00	90.	- 00	00.	0	2 5	9	900	00.	00.	\$	88	Pr	00	00.	3 3	90	98	60.	00.0	.00	8	80	8	800	8	96.	30	60.	-00	S 5	90	3	86.	38	3	- 1111
		10.	10°	10*	٠ د د	160	10.	10.	10.	10.	10.	10.	-	10.	4 3	16.	100	9	10.	130	10.	70.			7 6	10.	7.	#		16.	10.	10.	4	5 5	する	50.	100	.01	70.	10.	10.	4	10:	6	10.	17.	100	70°	100	.0	10.	3		
63	9 2	27	82	62	30	+	35	33	4	35	36	37		6 Е		7	75	:	*	94	47	9			16	53	2	\$	2.	7 4	2.6	9	#:	2 4	\$	\$	27	3	69	=	22	#	21	2 2	~	2	-	0	2	6	:	=	•	
61.5	02.	*. 30	0000	4.30	\$.09	1	5.20	5.30	5.40	5.50	6.00	6.10	0.50	6.30			2.10	7.20	7. 30	-	7.50	60.0	1	07.8	6.30	9.50	00.7	914	07.6	9.30	9.50	10.00		10.30	1040	10.50	60.11	11.20	11.39	11.50	12.00	- 414	12.20	12.50	12.50	13.00	1	13.20	13.30	13.50	14.09	02:01	07.41	
5	<u>ة</u>	10.1	10.1-	1001	10.1	1	10.1	10.1	10.1	10.1	10.1	100	10.4	10.1	1		1001	10.1	10.1	100	10.1	70:1	3	10.1	10.1	10.1	10.1	4	10.1	1001	10.1	10.1	4 3		4	10.1	0.0	10.1	10.1	10.7	1.01		10.1	1001	1001	1001	4	ē:	1004	1.01	10.1	5		77.47
			-																															7	н	S P		e i	IS,	E.	- 5													

055.	, ,	0.311	1450.	1834		2017.	3068-	31.43.	31336	3044.	2896.	2706.	2474	• 1 2 2 2	1786.	1614.	1469	1221	, , , , , , , , , , , , , , , , , , ,	1012.	414.	245	676.		547.	493.	900	364.	340.	366	****	262.	249.	236	I N B	% 60 19	Pr	rol = (302	bal Cre 291	bil eel 7	k 1	y	(e		am		1115.		
	• 3 •	90		70		10																			00.	6	00	.00	600	9 6		.00	00.	00	00		0,0		00.	00.	60	.00	00	00.	000	40.00	3.90		
	1.03		01.	2:	01.0		90		0	*6.	•0•	•0•	6		0.	٥.		. 5		10.	16.	 	6.	6	10.	ē:	į -	٤.	16.	5		٠،	٠ •	6	5	4	.	9	16.	70.	=======================================	ξ.	16.	•	⊅ ¢	•	4.09		
\$9.	92	.28	-12	-21.	71.	.00	20.	6	.05	• 0 •	• 05	50.	50.	00	.05	10.			0	10.	70.	, 5		9	٥.	ē :	ē	6.	4.	ē -		10.	٠ :	-	5	4	ē :	10.		ē:	- ē	10.	- 10	5.6		20.0	8.89	• •	9
234	232	237	238	239		242	743	544	245	246	247	248	249	26.1	252	253		25.6	252	258	259	2 7	262	263	564	265	267	268	269	27.0	***	273	274	276	277	2	622	787	282	283	285	286	- 282	298 200	5 6	0	NOS	DTAL VOLUME	- 1
15.00	15.10	15.30	*	05ª 5.7 	00.01	16.20	16.30	16.40	16.50	17.00	17.10	17.20	17.30	7.50	18.00	18.10		18.40	19.50	19.00	19.10	2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	19.40	19.50	20.00	20.10	20.30	20.40	-94.92	21.00	22.72	21.30	21.40	22.00	22,10	22.29	22.40	22.59	23.00	23.10	23.30	23.40	23.50	6	2 4	11	;	-H0UR 101	
1.02	7.05	1,02	1.02	1.02	70.1	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02		1.02	1,02	1.02	1.02	2	1.02	1.02	1.02	1.02	1.02	1.02	1.02	70-1		1.02	1.02	1.02	1.02	1485	20.1	1.02	1.02	1.02	20.	1.02	-1.02-			:	; ;	7.5	
•	•	•	•		.	•	,	•	: 🚅	<i>;</i>	;	•	• •			5.	•	• 4			٠.		•		.	• 0 7	11.	.11	124	• 77	**	.*1	.5.	16.	19.		<u>:</u> :	181	19.	.61	.02	21.		٠١,	, , ,	•	:	2	
70.	10:	.01	10.	10*	10.	10.	į -	: ō	50.	₽.	.01	٠٥.	รี จ	10.	.0.	10.		1 5		10.	10.	 		40	70.	70.	10.	10.	16.	5.5	=	10.	٠ :	200	10.	4:	~ =	10.	10.	٤.	10.	.01	٠ 10•	ē :	10.	5	;	٥	
38	00.	3	3	8.	0.	5 6	8	3	8	90.	69.	90.	5.5	3	Ş	90.	\$ 3	3 8	3	8	20.	8	3 5	00	00.	00.	0.0	0.	3	5 6	3	00.	3.5	8	60.	8	e 6	\$.00	۶. د	60.	60.	90*-	Ş.	2 8	•	i	PEAK	1143
, , , , , , , , , , , , , , , , , , ,	10.	10.	10.	101	10.	70.	٦	5	0	70*	10.	10.	5		10.	10.	3 3			10.	10.		10.	10.	10.	•01	10.	6.	30	3 6		10.	•	10	5.	•	10.			- - -	 	10.	7	<u>.</u>	 - -	:	· ;		675
₽ 6	0	26	6	4	6	9 6	5	?	100	101	102	103	*0	62	101	103	\$:	3 =		113	11	=======================================	711	=======================================	611	120	127	123	\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.\.	52	**	120	621	1	132	7	* : -		137	136	2	1+1	747			2			
24.44	15.00	15.20	15.30	73.47	15.50	00.01	2.4	16.30	10.40	16.50	17.00	17.10	17.20	30	17.50	18.00		14.30		16.50	14.00	10.20	19.30	1 0 4 0 P	19.50	20.00	02.02	20.39	20.00	20.50		21.20	21,39	21.50	22.00	1	97.22		64.22	23.00	67.67	61.30	1,		? †	:			
10.1	1.01	1.01	1:91	4	10.4	70.1		1001	1001	10.1	10.1	1.01	10.	5	10.1	10.1				1.0	10.1	=	101		10.1	1001	10.1	1.01			;		70	10	10.1	1	10:1	1	10.1	10.1		1.01		10.1			1		

THEOLIES INFO FOOD TOROGRAPH OATA THEOLIES INFO 0.00 1.00 1.00 0.00 0.00 0 0 0 0 0 0 0		TAUTO		CAL		R 11HP				VOL- 1.00	1	EXCS LOSS CONP 0	8	10.	10. 00.	10.	M B	20	302	::		.01 13.	.01	10.		
SUB-AREA RUNDER COMPUTATION TRIBUTARY INFLOR FLOOD HYDROGRAPH ISTAA ICONP IECON ITAPE JPLT JPRT HYDROGRAPH DATA TECH 100 0.00 1.00 1.00 0.000 TSTREA DLIVE RITIOL EAAIN STRES RITOR STRUCTURE MATERIAL STREET CA - 67.00 TSTREA DLIVE RITIOL EAAIN STRES TITOR STRUCTURE MATERIAL STREET CA - 67.00 TSTREA DLIVE RITIOL EAAIN STRES TITOR STRUCTURE MATERIAL STREET CA - 67.00 TSTREA DLIVE RITIOL EAAIN STRES RITOR STRUCTURE MATERIAL STREET CA - 67.00 TSTREA DLIVE RITIOL EAAIN STRES RITOR STRUCTURE MATERIAL STREET CA - 67.00 TSTREA DLIVE RITIOL OF PERIOD ORDINATES, TC - 67.00 TSTREA DLIVE RITIOL OF PERIOD ORDINATES, TC - 67.00 TSTREA DLIVE RITIOL OF PERIOD ORDINATES, TC - 67.00 TSTREA DLIVE RITIOL OF PERIOD ORDINATES, TC - 67.00 TSTREA DLIVE RITIOL ORDINATES, TC - 67.00 TSTREAD DLIVE RITIOL ORDINATES, TC - 67.00 TSTREAD DLIVE RITIOL ORDINATES, TC - 67.00 TSTREAD DLIVE RITIOL ORDINATES, TC - 67.00 TSTREAD DLIVE RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLOGIC RITIOLO)					5.00	. LAG= .63 236.	;	RAIN			•						1			ı	1	
SUB-AREA RUNDEF TRIBUTARY INFLOF FLOUD HYDROGRAPH 157 AQ 1000 HYDROGRAPH 157 AQ 1000 HYDROGRAPH 157 AQ 1000 HYDROGRAPH 158 AQ 1000 HYDROGRAPH 158 AQ 1000 HYDROGRAPH 158 AQ 1000 HYDROGRAPH 158 AQ 1000 HYDROGRAPH 158 AQ 1000 HYDROGRAPH 159 AQ 1000 HYDROGRAPH 150 AQ 1000 HYDROGRAPH 15	MP UTAT I OM	JPLT	0	0.000		RTIOKS	CN = 67.	DAT 63	A RTIOR-	C= 0.00 526.		DA HR.MM				l	i				į		ŀ		_	
TRIBUTARY INFLOR FLO 115TAO 1CO 115TAO 1CO 110TLO2 110TLO2 110TLO2 110TLO2 110TLO2 110TLO2 110TLO3 11	A RUNDFF	HYDROGRAPH IECON	0 4080080	1.00	STORM 0.00	LOSS RAIN ST	1.90 E	UM17	RECESSION ORCSN-	100 ORDINATES 642.		3							-	,-d		1				
	•			1.00	1 - 20		. 00 HETHES	10.		21 END OF 555.		EXCS L	96	90.3	6 0	90.	90	33	8 8.	90.	80	8.	3.	00.	30.	
		TRIBUTAR		THEOC TO		1 1	9			1145	ı		~		.	•	- 2:	12	==	51		91	0.2	21	67	

				<u> </u>	2 1		_		•	-						7	The state of the s	•			* E	THE PROPERTY OF THE PARTY OF TH	I					H R			The state of the s		5 7	3		10	**		•	i G	%	Pı Se	col	ba' Cr	um bi		ry ty						
1					2	- 4		•	9.	-2-	Ž	21.	29.		31.	93.	3	36.	37.	2	0	2		. 7 .	\$	į			464	•			•	-00	96	-	-16	926	3 5.	***************************************	•	12.				•	.221	114.		-	202.		361.
		10.			5	10		70.	16.	20.	- 05	.02	-05	0.5	-05	-02		, 02	20.	20	* 0	707	70.	20.	20.	20.		200	20.	- 92	20.	-02	5	10	10			100	5 6	ž.	~0.	• 05	- 05	200		~0.	60.	.03	•0•		2:	61.	• 20
	00.	.00	00	6.	000	0	0	00	00	10.	-	10.	10	70	10.	10.	=	5	٠. د	-	10.	4.			10.	16.			10.	10.		50.	.01	7 6	5	•	; ;	10.	ē. 6	5	6.	• 03	- 663	ָהָ הַ הַ		. 03	6	, 0	.07	6	=	• 10	
4	10.	9.	10.	10.	5	=	2	10.	10.	.03	03	.03	03	6	.03	• 03		60.	6.6	60	60.	6	5 6		6	• 03			0.	e e	5	• 03	6	5	.03	1	60.	-63	6	5 \$	6	•05	. 05		*	• 0•	.00		115	# =	\$ ~.	• 29	.65
***	1/1	172	- 113	17	175	~	178	1	180	181	187	193	184	507	991	187	-	681	061	202	143	4	6		198	661		707	502	50	502	202	208	250	112	# :	214	442	216		219	220	-127	222		522	226	8 ~ Z	526		212	233	234
27.4	4.30	04.4	50	9.00	5.10	200	5-40	5.50	00.9	6.10	6.20	6.30	04.0	950	7.00	7.10	22.4	2.30	04.	000	01.9	92.0		9	00.	01.6	25		8.0	00.01	200	10.30	00.01	11.00	11.10		11.40	44.50	00-21	200	12.30	17.40	-12,50	3.00		13.30	13.40	14.00	01.+1	14.20	14.40	14.50	15.00
	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	100	1.02	1.02	1.02	1.02	405	70.1	201	1.02	1.02	20.1	1.02	1.02	1.02	200	1.02	1.02	1.02	1.02		1.02	4402	1.02	20.1	1.02	1.02	1.02	70.1		1.02	1.02	1.02	1.02	1.02	1.02	70°1	1.02
	: .:	:		÷	. .	-	: :	: .:	: :	: :	: :		-		:	:،	4	. ;	.: .		:	•	<u>.</u>			:		-		.	;	: .:	.	-	::	-	: :		. .		: -:	;		•	: :	:	: .		:	•	: :	• • • • • • • • • • • • • • • • • • • •	-
10	10.	10.	10.	.91		10	10	10.	10.	10.	6	10.	10.	10	10.	10.	100	70.	ة .	10	10.	100	.		10.	10.			10.	70.	100	10.	10.	10	10.	ā		10.		100	10.	16.	101	10.		10.	:	70.	10.	£ .	10.	.01	10.
- 60	00	90.	3.	•00	8 8	8	8	8	90.	00	90	8	60	30	60.	00•		00	9	00	8	98	3 6	3	3	.00	8 9	3 9	3	8	B	8	9	90	8	8	3	3	9		3	90•	3.	9 0		00.	9	000	• 00	\$	9	9	00.
14	10.	70.	100-	10.	5	1		101	10.	10.	10	10	10	9	10.	70.	4	70.	- - -	0	70,	-	7 6		50	7. 101	1		7.	70.	2	0.	10.	10.	70.	=		100	٠ •		ē.	10.	100	1 0		70.	70.	10.	10.	10.	70.	7	10.
*	50	2.2	28	2	2 ;	2		1	32	96	2		96		7	45	+	*	÷ :	3	7	\$	÷ .	* 4	? ;	5	\$:	2, 2	*	5 .		3	G :		3		9 9	*	Z ;	2	2	72	2:	- 2	*	0	19	7 P	•	5 2	6.	P0	•
4	07.4	4.30		1.50	2.00			•	5.50	•	•	•	10		6.50	2.00		7.20	2.30	2.50	00.	-	97.9		250	0000		0.30	9249	9.50		02.01	19,30	10.40	00-11		11,30	-	11.50		12.20	•	•	14.00		13.20	13.30	13.50	10.00	97:01	14.30	0+1+1	14.50
1		10.1	10.1	1.01	10:	10,1	9		1001	10-1		10-1	6		10.1	10.1		10.1	100	10.1	1.01	1	100			1.01			-	5.		1:0:	10.	10.7	:		10:1	4.4	7.07		10.1	1.01	100			1001	70.1	10:1	10.1	-	1.01	10.1	10.1
			f :																		l ņ																			4							:					:	

257. 304. 575. 1287.	975. 175. 1267.	1287.	1287.		* (O T)			7040	657.	527.	451.	200		224.	204.	682				6 T V	40.0	•	44	43.	-15	•		47.		• •	46.	46.	40.	46.		Out 1% Good MO B2	Pr Sec	rob e (at re	il ek	it	у				
2.		•		• 00	20.	30.	5		5	10.	:	= =		50.	٥.		6	8	8	00	8	00.	8	8	8	8		00.	6 8	00	8	00.	8	00	00.	8	.09	9	8		? 6	00	9	0.00		200
•				•23	9				.04	•				46	•			-	5	10.	10.	10.	=	6.	10.	ē		16.	ē :	6.	ē	5	10.	6	10.	6.	10.	10	.0	4	: 6	-01	10.	0.00		126-11
				• 28	21:	21.	, 0		.07	.0.	50.		6	• 02	5	2	5	4	ē :	10	10.	5	 	6.	10.	ē		10.	ē.	5	ē 6	ē.	ة. و	10.	.01	6	10.	10	5	100	; ;	70.	9	00.0		224-11
,	233	234		237	238	***	7 7		243	**2	245	9 7	248	548	250	23	253	787	522	262	258	520	1	292	263	264		267	26.8	270	271	273	274	276	277	27.0	280	281	283	487	78 2	287	289	280		5
) · · ·	14.58	00.61	2.5	15.30	15.40	15.56	06-91	10.20	16.30	16.40	16.50	00-71	17.20	17.30	05.21	e c	21.61		18.30	19.40	00.61	01.61	۲,	04.61	19.50	20.00	2000	20.30		21.00	21.10	21.30	21.40	22.00	•	22.30	~	, , , ,		٠,	23.40	23.50	00.0	01.		
70.1	1.65	1.02	20.1	1.02	1.02	20.1	20.1	20.	1.02	1.02	1.02	70.1	20.1	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	20	1.02	70.7	1.02	20.1	1.02	1.02	1.02	1.02	1.02	1.02	1.02	1.02	20.1	1.02	20.1	1.02	200	1.02	1.02	1.03	1.03		
•	د نيا د	<u>.</u>	: :	:	. .		: -		: :	:	:	• -	: -	: -:	٠.		: ?		~	 2	3.	3.	-		3	ń d	•	;	; .	•	•	٠,	٠. ،	5.			;	•	; ;		• •	•	: .	٠,	<u> </u>	•
70.		.		.01	10.	701			10.	10.	70.	5.5	7	.01	10.	10	10.	-	70.	10.	10.	10.	10	101	10.	70.		6.	10.	5	10.	10.	10.	10.	10.	9 5	10.	3 6	10.	3 3	10.	10.	10.	10.		
99.	* *	9		00.	9	3 8	3 8	3	8	00•	3	3 8	30	00.	90.	3 8	3	*	8	9	8	00.	3 8	00	8	8 8	3	00.	90.	0	8	8	9	00	00.	3	• 00	3 6	3	3 8	? 6	3	000	6. 9		
-	: 10°	?		10.	5	100	1 6		10.	70.	10.	ě		100	70.	3		-	٠ و	10.	10.	10.	=	70.	4	70.		10.	10.	10.	10.	10.	10.	10	10.	5	10.	3 6	16.	1	: 0	707	1	10.	•	
~	3	6		76	£ (6			6	80	2 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	701	101	5 01	2	108	\$	2:	111	113	11	=	117	377	617		122	123	125	126	129	621	131	132	į	135	* =	1 38	3	141	142	3		:	1
14.30	- 14141	14.50	92.6	15.20	15.30	49,44	12.30		16.20	16.30	10.40	10.50	97.7	17.20	17.30	67.2.	00.0	1	07-91	16.30	19.50	19.00	97.01	19.30	9444	19.50		20.20	20.30	20.50	21.00	21.20				•	22.30	05.2	23.00	97.7	23, 30	21.40	23.50	00.00		
10.1	1011	6 i		1.01	10.4	-1:01			1001	1.01	1.01	3		1.01	101	-	-	+	1.01	10-1		10.1	1		-	10.1		1.01	101		10.1	10:1	1001	-	1.01	=	10.1	6.	10.1	4 5	10:1	-		70		

•		• ~ •	• •	3 9	2.2.3			****		8 8 8 9			V X 2	Ot 17	ıtpu	t Sunn	mary	Even	
														Gc MC B2	ose) 3	Cree 0297	k Lal	ke Dar	n
														TINE OF FAILURE HOURS	00.0				
		PER SECONDI	AREA	3.76	00-1	2.59	4.78	7.79				OF DAM 752.30	1881.	TINE OF MAX OUTFLOW	42.17				
		C METERS	72-H0UR	245.		1.864	311.	219.			ANALYSTS	. ST T00		DURA TION OVER TOP MOURS	00.00				
		SIC FEET PER SECOND (CUBT MILES(SQUARE KILOMETERS)		487.		3.69	617.				DAN SAFETY AN	SPILLWAY CRE	0	MAXINUM OUTFLOW GFS	1715.			200	
		UBIC FEET P E MILFS150U	K 6-HOUR			++69*11	1926.				SUMMARY OF D	AL VALUE	•	HAXINUM STORAGE AC-FI	1885.				
		AGE FLOW IN CUBIC Area in Square Hii	PEA	.01 3143.	•	127	.04 3725.	DAM 1715.			\$	INITI		HAXIMUH DEPTH OVER-DAN	00.00				
		SUMMARY, AVERAGE		APH AT INFLOI	C0 1371 14 F04		INEO INFLOW	10 0				ELEVATION	QUTFLOW	MAXINUM RESERVOIR No Suelev	751.95				
	1 1	RUNDEF SUM		HYDROGRAPH	200 CO 27	40000E	2-CONBINED	ROUTED				1		RATIO OF PMS	00.00				
											A A A	PLAN							

DATE ILME